

Environmental Solutions

Assessment – Engineering – Management

ASBESTOS ABATEMENT MONITORING REPORT

**(UNDERGROUND TRANSITE PIPES)
(HARBOR GATEWAY)**

PREPARED FOR:

BOEING REALTY CORP.

PREPARED BY:

**MICHAEL REZVANI, REA, CAC
PRINCIPAL CONSULTANT**



AUGUST 27, 2001

Environmental Solutions

Assessment - Engineering - Management

**August 27, 2001
Project No. ES00-005.Rpt**

**Mr. Johnny Marasco
Boeing Realty Corporation
3760 Kilroy Airport Way
Suite 500
Long Beach, California 90806**

**Class II Asbestos Abatement Monitoring Report
Underground Transite Conduit & Pipes (Phase III)
Boeing @ Gateway
19901 Normandie Avenue
Los Angeles, California**

Introduction: Approximately 5000 feet of 4" and 5" diameter asbestos transite pipe encased in concrete were uncovered from underground at the subject site for abatement. The concrete encase asbestos transite pipes were placed in an assigned areas northeast and northwest of the subject site by Boeing's demolition contractors for proper handling, abatement and disposal. This report presents the results of our daily observations and air monitoring of the subsequent class II asbestos abatement performed by Tri-State Restoration, Inc. (aka, PDG, Tri-State). The abatement started on January 29, 2001 and completed on August 23, 2001.

Project Summary: Tri-State Restoration was retained by Boeing Realty Corporation to perform the class II asbestos abatement. The abatement was performed in accordance with the approved asbestos abatement specification prepared by Environmental Solutions for such project.

As a general state of practice, the transite pipes and conduit were cut-out by heavy equipment in transportable sections and placed in an area called the regulated work area (RWA) for abatement. This area was properly demarcated with caution tapes and was measured to be approximately 5,000 square feet. The RWA during the first phase of the project was located in the northeast of the subject site and during the second phase of the project, the RWA was removed and transported to the northwest of the site due to progression of the construction project.

Each concrete section containing transite pipes was carefully broken in sections which could be further handle by abatement personnel. The transite pipes were then separated from the surrounding concrete encasement, first, by the use of a large jack-hammer and then manually by asbestos abatement workers using hammer and chisel. In general, the process of this asbestos abatement included three different phases. 1) breaking the concrete, containing transite pipes while controlling the spread of transite pieces, 2) to separate and collect all pieces of transite pipe attached to the concrete encasement and properly disposing the transite in asbestos bags, and 3) to perform two final clearance sweeps of the RWA from east to west in order to find and collect much smaller pieces of transite prior to releasing the site to Boeing.

Environmental Solutions monitored the abatement activities on daily basis. The abatement activities were generally consistent and redundant in nature. Air samples were generally collected for determination of asbestos fiber concentration levels around RWA. Air samples were collected daily using low-flow air pumps at the northeast and the northwest corners which were in most cases downstream of the wind-flow from the RWA. The air samples were analyzed daily by phase contrast microscopy (PCM) using NICSH 7400 method for detection of asbestos fibers in the filters. The air sampling documentation is presented in exhibit II of this report.

Final visual clearance was performed at the completion of the final sweep on August 23, 2001. The RWA was found to be free of visible pieces of transite debris. No assessment of the soil conditions was made or deemed warranted for this project. All transite materials were bagged and sealed and placed in an approved bin for transport to an approved land-filled by BDC transport (see attached hazardous manifests).

Conclusion: Tri-State workers were protected by tyvek suits, half-face respirators and hard hats for the duration of this project. No accident was observed or found recorded during this project. Visible emissions were kept to a minimum by the use of a water-tank truck used around and in the vicinity of the RWA. We believe that the abatement procedures were satisfactorily performed in accordance with 29 CFR 1926.1101 for handling and disposal of non-friable asbestos containing materials (class II) such as transite pipes.

The following exhibits are included and complete this report.

- o **Exhibit I** Field Reports
- o **Exhibit II** Air Sample Documentation
- o **Exhibit III** Hazardous Manifests




EXHIBIT I

FIELD REPORTS

Environmental Solutions
Assessment - Engineering - Management



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-005

Project Name BOEING REALTY CORP.

Shift Start Date 01/29/2001

Project Location: N.E. CORNER / UGTP

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

- * 10:30 AM / TRI-STATE w/ A CREW OF SIX MEN ON-SITE.
OUR OBSERVATIONS OF CONDITIONS INDICATE THE FOLLOWING;
- * APPROXIMATELY 60 CUBIC YARDS OF ENCASE/CONCRETE BLOCKS OF TRANSITE HAS BEEN BROUGHT DOWN TO THE WORK AREA FROM BUILDING "3".
 - * THE NEW BLOCKS FROM BUILDING 3 ARE MARKED FOR "ID".
 - * THE LENGTH OF TIME OF COMPLETION HAS BEEN EXTENDED.
 - * THE RECENT RAINS HAVE CAUSED A SIGNIFICANT REDUCTION OF DUST EMISSIONS IN GENERAL.
 - * NO AIR AMBIENT SAMPLING IS WARRANTED.
 - * THE WORK CONTINUOUS TO BE PERFORMED BY THE USE OF HEAVY EQUIPMENT.
 - * AGENDA VISITED THE SITE LAST THURSDAY & HAS FOUND THE GENERAL WORK AREA ACCEPTABLE.
 - * NO ACCIDENT IS REPORTED.

MIKE REZNANI
FIELD TECHNICIAN (Print Name)

Mike Reznani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 01/30/2001

Project Location: N.E. CORNER / UGTP

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:00 AM / -TRI-STATE W/ A FIVE-MAN CREW ON-SITE.
THE SCOPE OF WORK FOR THE WORK TODAY IS TO CONTINUE
W/ THE SPECIFIED ABATEMENT @ THE REGULATED WORK AREA.
THE PROCESS OF BREAKING THE CONCRETE INCASEMENT AROUND
THE TRANSITE PIPES IS BEING PERFORMED W/ CARE ON A
SPECIAL DROP CLOTH WHICH CONSISTS OF TWO LAYERS OF 10'
POLY ON TOP OF THE LAYER OF PLTWOOD WHICH IS PLACED ON
A LARGE & THICK PLANE OR PLATE OF STEEL, FOR FIRMNESS.
NO PARTICULAR EMISSION FROM THIS PROCESS IS VISIBLE.
A MEMBER OF ACMD HAS VISITED THE SITE FOR INSPECTION OF
PROCESSES IN THE AREA WHERE OTHER CONTRACTOR ARE CRUSHING
BRICKS & CONCRETE. THE ACMD INSPECTOR HAS FOUND THE
ASBESTOS ABATEMENT PROCESS SATISFACTORY.
MORE TRANSITE CONTAINING CONCRETE CASING IS BEING ADDED TO
THE PILE ON REGULAR BASIS.
NO ACCIDENT WAS REPORTED DURING THIS SHIFT.

Mike DeZavani
FIELD TECHNICIAN (Print Name)

1/30/2001
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 02/05/2001


Project Location: N.E. CORNER / UGTP


Contractor: TRI-STATE

Weather Condition: CLEAR & WARM

DESCRIPTION:

- * 10:30 AM / TRI-STATE w/ A SIX MAN CREW ON-SITE.
OUR OBSERVATIONS INDICATE THE FOLLOWING:
- ♦ BAGS CONTAINING TRANSITE REMAIN IN RWA ALL SEALED.
 - ♦ HAMMERING & BREAKING CONCRETE BLOCKS CONTAINING TRANSITE PIPE CONTINUE w/ HEAVY EQUIPMENT.
 - ♦ SEPARATION OF CONC. & TRANSITE CONTINUES MANUALLY INSIDE RWA.
 - ♦ THE RWA REMAINS MARKED w/ ACM SIGNS & BARRACADES.
 - ♦ THE AREAS OUTSIDE OF RWA ARE AS BEFORE. NO CROSS CONTAMINATION BY TRANSITE HAS BEEN OBSERVED.
 - ♦ NO ACCIDENTS ARE REPORTED.
 - ♦ THE ABATEMENT WORK APPEARS ABOUT 30% COMPLETE.
 - ♦ THE CREW TAKES ONE WICH BREAK.
 - ♦ THE ACM BIN IS ABOUT 50% FULL.


FIELD TECHNICIAN (Print Name)


Mike & Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ED00-005

Project Name BOEING REALTY Corp.

Shift Start Date 02/07/2001

Project Location: N.E. CORNER / UGTP

Contractor: TE1- STATE

Weather Condition: CLEAR & MILD.

DESCRIPTION:

- * 11:00 AM / TE1-STATE w/ A SIX MAN CREW ON-SITE
OUR TODAY'S OBSERVATIONS OF THE RWA INDICATES.
- * MANUAL CONCRETE BREAKING FOR TRANSITE RETRIEVAL CONTINUES
 - * BAGS ARE LEFT @ RWA OUTSIDE. THESE BAGS CONTAIN TRANSITE PIPE PIECES & ARE SEALED CLOSED.
 - * SEPARATION OF CONCRETE & TRANSITE CONTINUED MANUALLY INSIDE RWA.
 - * THE WORK AREA REMAINS MARKED & BARRACATED.
 - * TRUCK TRAFFIC IS CARRYING DUST EMISSIONS THAT BLOW ACROSS RWA.
 - * THE COMPLETION STU IS @ 30% POINT.
 - * THE ONLY BIN @ N.E. CORNER IS 50% FULL.
 - * NO ACCIDENT IS OBSERVED OR REPORTED.
 - * THE ADAMENT PROCESS & PERSONNEL PROTECTION APPEARED SATISFACTORY DURING THIS SHIFT.

MIKE REZANI
FIELD TECHNICIAN (Print Name)

Mike Rezani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E800-005

Project Name BOEING REALTY CORP.

Shift Start Date 2/22/01

Project Location: UGTP

Contractor: TRI-STATE

Weather Condition: CLOUDY & WINDY

DESCRIPTION:

* 10:30 AM / TRI-STATE w/ A CREW OF 5 MEN ON-SITE.
THE TRANSITE ABATEMENT IS IN PROGRESS.
THE ABATEMENT COULD NOT BE PERFORMED LAST WEEK DUE TO
RAIN & MUDDY CONDITIONS. ALSO LAST MONDAY 02/19/01 WAS
NOT A WORK DAY & THEREFORE THE ABATEMENT WORK IS FALLING
BEHIND. TODAY IS THE THIRD DAY OF PRODUCTIVE WORK.
THE GROUND IS STILL MUDDY & SATURATED.
THE BREAKING UP THE CONCRETE CASING CONTINUES w/ HEAVY
EQUIPMENT & ABATEMENT CONTINUED w/ BY HAND. BAGS OF
ASBESTOS ARE HAND CARRIED TO THE HOT DO BIN.
SEVERAL MANIFESTS HAVE BEEN EXECUTED & COPIES HAVE BEEN
SUBMITTED TO US FOR PROPER FILING FOR THE FINAL REPORT.
* NO VISIBLE EMISSIONS IS DETECTABLE ANYWHERE ON THE SITE.
* NO ACCIDENT IS REPORTED OR OBSERVED.
* COMPLETION DATE IS @ APPROX. 30%.
* AIR SAMPLING IS NOT DEEMED NECESSARY.
* TRI-STATE CONTINUES TO COLLECT PERSONAL AIR SAMPLES.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ESOC-005

Project Name BOEING REALTY CORP.

Shift Start Date 01/16/2001

Project Location: UNDERGROUND TRANSITE

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD.

DESCRIPTION:

* 10:15 AM / ENVIRO-SOLUTIONS ON-SITE. THE TRI-STATE CREW OF FIVE MEN IS ON-SITE. CONCRETE

THE WORK INCLUDES EXCAVATION OF ENCASED TRANSITE PIPES FROM UNDERGROUND & ABATING THE ASBESTOS CONTAINING TRANSITE PIPES. THE AREA OF WORK IS @ THE NORTHEAST CORNER OF THE SUBJECT SITE IN AN ISOLATION SECTION.

OUR OBSERVATIONS INDICATE, THAT THE REGULATED WORK AREA (RWA) HAS BEEN ESTABLISHED BY TRI-STATE & THE AREAS BEYOND THE RWA HAVE BEEN DEMARCATED & BARRICDED BY ASBESTOS TAPE & BARRELS.

SEVERAL HEAVY EQUIPMENT ARE USED FOR THE PROCESS OF THE EXCAVATION & SEPARATION & ABATEMENT.

THE BREAKING OF CONCRETE CASING TAKES PLACE ON A LARGE STEEL PLATE PLACED ON A 600 ft² - 800 ft² 20 MIL FOAM. A LARGE JACK HAMMER BREAKS THE CONCRETE WHILE THE WORKERS PICK UP & SEPARATE THE ASBESTOS PIPES.

MUCH WATER IS USED IN THE PROCESS TO REDUCE EMISSIONS.

THE WORKERS ARE PROTECTED BY / TUXE SUIT, RESPIRATOR, GLOVES, GOGGLES, BOOTS & HARD HATS.

NO ACCIDENTS WERE OBSERVED OR REPORTED.

Mike Iezzani
FIELD TECHNICIAN (Print Name)

1/16/2001
SIGNATURE DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 01/18/2001

Project Location: UNDERGROUND TRANSITE

Contractor: TRI-STATE

Weather Condition: CLEAR & COOL.

DESCRIPTION:

- THE OBSERVATIONS INDICATE THE FOLLOWING:
- * 10:40 AM / ENVIRO. SOLUTIONS ON-SITE.
 - TRI-STATE w/ 5 MEN & A SUPERVISOR ON-SITE.
 - THE SCOPE OF WORK HAS NOT CHANGED.
 - THE BOUNDARIES OF THE RWA REMAINS IN PLACE.
 - WORK CONTINUES TO BE DONE BY HEAVY EQUIPMENT.
 - NO EMISSIONS OTHER THAN HAMMERING @ THE CONCRETE IS OBSERVED.
 - AIR SAMPLES COLLECTED ON TUESDAY DO NOT INDICATE ANY CONCENTRATION LEVELS GREATER THAN 0.01 f/c.
 - NO ACCIDENTS WERE REPORTED.
 - WORK IS @ 5% COMPLETION.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-005

Project Name GARBOING REalty Corp.

Shift Start Date 01/22/2001

Project Location: UNDERGROUND TRANSITE

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:30 AM / ENVIRO. SOLUTIONS ON-SITE THE SCOPE OF WORK IS STILL UNCHANGED.

BLOCKS OF CONCRETE ARE BEING BROKEN BY HEAVY EQUIPMENT / JACK-HAMMER @ A BREAKING STATION & ACM TRANSITE PIECES ARE BEING COLLECTED & BAGGED BY THE CREW. THIS IS A SLOW PROCESS BUT IS DONE IN A SAFE MANNER.

THE CREW IS WELL PROTECTED & PLENTY OF WATER IS INCORPORATED INTO THE PROCESS.

NO AIR SAMPLING IS DEEMED NECESSARY SINCE NO CONTAMINANT IS APPLIED.

NO ACCIDENTS WAS REPORTED DURING THIS SHIFT.

10% OF PROJECT HAS BEEN ACCOMPLISHED.

Mike Rizman
FIELD TECHNICIAN (Print Name)

1/22/2001
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 03/05/2001

Project Location: UGTPR

Contractor: TRI-STATE

Weather Condition: Cloudy & RAIN

DESCRIPTION:

* 10:30 AM / ENVIRO SOLUTIONS ON-SITE.
TRI-STATE w/ A FIVE-MAN CREW ON-SITE.
THE GROUND IS VERY WET & THE SOIL AROUND THE SITE HAS TURNED TO MUD.
TRI-STATE CREW IS TRYING TO GET THE HEAVY EQUIPMENT OPERATING AGAIN & PREPARE THE PADA.
THE DARRIER- ASBESTOS TAPES ARE REINFORCED.
& A FEW CONCRETE BLOCKS ARE PLACED @ CONCRETE BREAKING PAD.
THE RAIN CONTINUES TO FALL INTENETANTLY.
DURING THIS SHIFT FIVE BAGS OF TRANSITE PIPES WERE SEPARATED & PLACED IN THE BIN.
AIR MONITORING WAS NOT NECESSARY, SINCE NO EMISSIONS WERE PRESENT DUE TO RAIN.
NO ACCIDENTS WERE REPORTED.
NEXT SHIFT IS MARCH, THU.

Michael Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-005

Project Name BOEING REALTY Corp.

Shift Start Date 03/08/2001

Project Location: US TPR

Contractor: TRI-STATE

Weather Condition: PARTLY CLOUDY

DESCRIPTION:

- * 10:40 AM / TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
THE SCOPE OF WORK IS TO
- * BREAK FIVE TO SEVEN LARGE CONCRETE BLOCKS &
REMOVE ACM TRANSITE PIPE FROM THE BLOCKS & BAG-OUT.
- * THE GROUNDS ARE STILL MUDDY &/OR DAMP.
- * NO EMISSIONS ARE DETECTED.
- * NO AIR SAMPLES ARE NECESSARY.
- * NO ACCIDENTS ARE REPORTED.
- * WORKERS TOOK ONE LUNCH BREAK FOR ONE HOUR.
- * ALL ACM REMOVED DURING THIS SHIFT IS BAGED.
- * THE ABATEMENT COMPLETION RATE IS @ 35%.
- * ALL BARRIERS ARE INTACT & PMA IS RESTRICTED.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 03/12/2001

Project Location: UG/TRANSITE

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

- * ENVIRO. SOLUTIONS ON-SITE @ 10:50 AM.
THE SCOPE OF WORK REMAINS THE SAME.
 - * THE PVA ISAPLERS ARE IN PLACE & ESTABLISHED.
 - * THE CREW IS GETTING READY FOR LUNCH BREAK.
 - * THE CREW IS AWKWARDING ABOUT 5 LARGE BLOCKS FOR TRANSITE ABATEMENT EVERY DAY.
 - * THE CHALKY SOILS ARE DRY & DUSTING IS A POSSIBILITY.
 - * NO DUST EMISSIONS IS DETECTED IN OR AROUND THE WORK AREA.
 - * WORK CONTINUED AFTER LUNCH BREAK.
 - * NO ACCIDENTS IS REPORTED OR OBSERVED.
 - * ALL REMOVED TRANSITE HAVE BEEN BAGGED & PLACED IN THE BIN.
- * 12:38 ENVIRO. SOLUTIONS OFF-SITE.

MIKE REZVANI

FIELD TECHNICIAN (Print Name)

Mike Rezvani

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 03/15/2001

Project Location: UWTZ

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 12:00 / TRI-STATE w/ FIVE MEN ON-SITE.
ENVIR. SOUTIONS ON-SITE FOR MONITORING.
THE STATUS OF THE PROJECT HAS BEEN THE SAME.
TRI-STATE CONTINUES TO BREAK & ABATE ASBESTOS PIPES
OUT OF 6 LARGE CONCRETE BLOCKS EVERY DAY.
THE WORKERS ARE PROTECTED w/ PERSONAL PROTECTIVE
EQUIPMENT.
TODAY, THERE ARE MUCH GRADING & DIRT REMOVAL ACTIVITIES
ADJACENT TO THE ASBESTOS ABATEMENT WORK AREA &
SOME DUST IS MIGRATING INTO OUR WORK AREA AS
THE RESULT.
NO VISIBLE DUST EMISSIONS IS DETECTED AS THE RESULT
OF ABATEMENT.
NO ACCIDENT OR OTHER MISHAPE HAVE BEEN RECORDED
OR NOTICED SO FAR.
THE WORK COMPLETION IS @ 45% POINT.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-025

Project Name BOEING REALTY Corp.

Shift Start Date 3/19/2001

Project Location: LIGHT ABATEMENT

Contractor: TRI-STATE

Weather Condition: CLEAR & WARM

DESCRIPTION:

* 10:30 AM / TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
THE SCOPE OF WORK IS UNCHANGED.

THE BREAKAGE OF THE LARGE BLOCKS OF CONCRETE w/
TRI-MIX PIPES CONTINUES.

TODAY THE WEATHER IS MUCH WARMER & DRY.

THE EMISSIONS ARE MORE VISIBLE FROM THE EXCAVATION AREA,
ADJACENT TO OUR WORK AREA.

THE JACK HAMMERING OF THE CONCRETE BLOCKS IN OUR WORK
AREA IS NOT RELEASING VISIBLE DUST EMISSIONS SINCE WATER
IS BEING USED BY TRI-STATE.

THE CREW TOOK ONE LUNCH BREAK @ 11:00 AM.

NO ACCIDENTS WERE REPORTED.

NO UNUSUAL OR MISHAP ACTS WERE OBSERVED.

PROJECT IS EXPECTED TO COMPLETE BY 30 MORE WORK SHIFT.

Mike Rezvan
FIELD TECHNICIAN (Print Name)

Mike Rezvan
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E800-605

Project Name BOEING REALTY Corp.

Shift Start Date 3/20/2001

Project Location: UGTP ABATEMENT

Contractor: TEI-STATE

Weather Condition: PARTLY CLOUDY

DESCRIPTION:

* 10:45 AM / ENViro. SOLUTIONS ON-SITE.

TEI-STATE w/ A SIX MAN CREW ON-SITE.

SINCE YESTERDAY'S SHIFT, ABOUT 300 FEET OF CONCRETE BLOCKS CONTAINING ACM (TRANSITE) HAS BEEN BROUGHT OUT FROM UNDERGROUND & ADDED ONTO THE RWA PILE.

THIS WILL EXTEND THE LENGTH OF ABATEMENT WORK.

THE CREW PERFORMS THE ABATEMENT PROCEDURES ACCORDINGLY.

ONE AIR SAMPLE IS COLLECTED DOWNSTREAM OF WIND.

THE CREW TOOK ONE LUNCH BREAK.

NO ACCIDENT WAS OBSERVED OR REPORTED DURING THIS SHIFT.

NO VISIBLE EMISSIONS WAS OBSERVED RISING FROM THE RWA.

MIKE REVVANI
FIELD TECHNICIAN (Print Name)

Mr. J. D.
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY Corp.

Shift Start Date 3/22/2001

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: PARTLY CLOUDY

DESCRIPTION:

* 10:40 AM / ENVIRO. SOLUTIONS ON-SITE.
TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
THE OLD PILE OF CONCRETE & THE NEWLY ADDED WORK-
PILE IS/ARE SAGGREGATED.
THE COMPLETION RATE OF THE ORIGINAL PILE OF TRANSITE
IS @ 20% & THE NEW PILE HAS NOT BEEN WORKED ON.
DUST EMISSIONS CONTINUE TO BE VISIBLE FROM THE GRADING
AREA SOUTH OF THE RWA.
THE WORKERS ARE PROTECTED & THERE ARE/IS NO VISIBLE
EMISSIONS FROM THE ASBESTOS WORK AREA.
DUE TO DUST FROM THE GRADE/CONSTRUCTION AREA, TRI-STATE
IS NOT SUBMITTING PERSONAL AIR SAMPLES FOR TIME BEING
NO ACCIDENTS REPORTED THIS SHIFT.
THE WORK IS PROGRESSING WELL.

Mike Revani
FIELD TECHNICIAN (Print Name)

Mike Revani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-005

Project Name BOEING REALTY CORP.

Shift Start Date 03/26/01

Project Location: UGTP ABATEMENT

Contractor: TRI-STATE

Weather Condition: CLEAR & BREEZY

DESCRIPTION:

* 1100 AM / TRI-STATE w/ A SIX-MAN CREW ON-SITE.
THE WINDS ARE BLOWING OUT OF SOUTH / SOUTHWEST &
THIS, SOME DUST FROM THE SOUTH OF THE PROPERTY IS
VISIBLE @ TIME.

THE SCOPE OF WORK REMAINS THE SAME.

THE CREW IS TAKING LUNCH BREAK @ THIS TIME.

THE RWA APPEARS TO BE IN ORDER.

THE TRANSITE BREAKING AREA IS ALSO IN GOOD ORDER.

THE PROGRESSES IN GOOD MANNER.

NO ACCIDENT WAS REPORTED DURING THIS SHIFT.

ONE AIR SAMPL WAS COLLECTED @ DOWNSTREAM OF RWA

Mike Resani
FIELD TECHNICIAN (Print Name)

Mike Resani
SIGNATURE

DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 03/28/2001

Project Location: UGTP ARATEMENT

Contractor: TRI-STATE

Weather Condition: CLEAR & MIL

DESCRIPTION:

- * 10:38 AM / TRI-STATE w/ A CREW OF SIX MEN ON-SITE.
OUR OBSERVATIONS INDICATE THE FOLLOWING;
- ♦ THE RWA IS SECURED & DEMARKATED.
 - ♦ THE RWA IS BEING KEPT WET TO PREVENT DUST EMISSIONS BECOMING VISIBLE.
 - ♦ TRI-STATE SUBMITTALS THREE HAR. MAT MANIFEST & ONE NON-HAR MANIFEST FOR FILING.
 - ♦ THE WINDS ARE OUT OF THE SOUTH & THE GRADING ACTIVITIES TO THE SOUTH ARE CREATING LOTS OF DUST.
 - ♦ THE CREW TAKES ON LUNCH BREAK.
 - ♦ completed RATE OF THE FIRST PHASE IS @ 70%.
THE WORK ON THE SECOND PHASE HAS NOT STARTED.
 - ♦ NO ACCIDENTS WERE RECORDED.
 - ♦ NO ADVERSE CONDITIONS EXIST.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name Boeing Realty Corp.

Shift Start Date 03/29/01

Project Location: UATP Removal

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

- * 10:30 AM / ENVIR. SOLUTIONS ON-SITE.
TRI-STATE w/ A CREW OF SIX ON-SITE.
WORK AS VISUALLY OBSERVED INDICATE THE FOLLOWING:
- ALL FIVE WORKERS ARE @ PWA CONDUCTING CARBON
BREAKAGE OF CONC. BLOCKS, SEPARATING TRANSITE PANELS
BACKING FORM, TRANSPORTING BAGS & KEEPING ORDER.
 - MEETING w/ J. MARASCO ABOUT PROGRESS REPORT.
 - ONE AIR SAMPLE IS COLLECTED D.S..
 - THE GENERAL WORK AREA IS DUSTY.
 - NO VISIBLE EMISSIONS DETECTABLE FROM THE ABATEMENT
AREA.
 - NO ACCIDENTS REPORTED.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-025

Project Name BOEING REALTY Corp.

Shift Start Date 4/3/2001

Project Location: UGTP Removal

Contractor: TRI-STATE

Weather Condition: CLEAR/PC & Cool
BREEZY.

DESCRIPTION:

* 10:40 AM / TRI-STATE W/ A CREW OF THREE MEN ON-SITE.
THE SCOPE OF WORK REMAINS THE SAME.
THE CREW'S WORK REMAINS TO BE REMOVAL BY SEPARATION
OF BAGGING.
THE WORK IS PROGRESSING RATHER SLOWLY DUE TO WINDY/
BREEZY & COOL CONDITIONS.
NO CROWDING ACTIVITIES ARE OBSERVED ON THE ADJACENT
PARTS.
NO EMISSIONS ARE OBSERVED FROM THE RING OR THE
ADJACENT WORK AREAS.
ONE WHICH BREAK IS TAKEN BY CREW.
NO ACCIDENTS SEEN OR REPORTED.
ONE MONITORING AIR SAMPLE COLLECTED.

THOMAS PREVAN
FIELD TECHNICIAN (Print Name)

Tom Prevan
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-005

Project Name BOEING REALTY CORP.

Shift Start Date 04/05/2001

Project Location: UGTP ADJUSTMENT

Contractor: TRI-STATE

Weather Condition: P/C & COOL / BREEZY

DESCRIPTION:

* 10:48 AM / TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
THE SCOPE OF WORK REMAINS THE SAME.
SINCE LAST WEEK, THE CREW HAS BEEN WORKING ON THE NEWLY
UNCOVERED TRANSITE PIPES.
THE WEATHER IS COLD & BREEZY, THE GRADING WORK IS
BEING DONE TOO FAR AWAY FROM THE ASBESTOS RWA &
THEREFORE AIR SAMPLING WAS SATISFACTORILY PERFORMED w/
GOOD RESULTS.
* NO ACCIDENTS WERE REPORTED.
* THE CREW TOOK ONE LUNCH BREAK & TWO SMALL/SHORT
BREAKS.

Mike Rezvanian
FIELD TECHNICIAN (Print Name)

Mike Rezvanian
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-005

Project Name BOEING REALT CORP.

Shift Start Date 04/09/01

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: CLEAR TO PARTLY CLOUDY

DESCRIPTION:

* 10:30 AM ENVIRON. SOLUTIONS ON-SITE.
TRI-STATE w/ A CREW OF FIVE ON-SITE.
THE CREW IS STILL WORKING ON THE ORIGINAL SCOPE OF
ABATEMENT WHICH IS THE FIRST LARGE PILE OF TRANSITE PIPES.
THE COMPLETION RATE OF THE ORIGINAL PILE IS EXPECTED TO
FINISH BY APRIL 25TH. THEY ARE @ A 85% COMPLETE
RATE @ THIS TIME.
THE PROCESS OF ABATE APPEARS TO BE RUNNING WELL W/O
INCIDENT.
THE GROUND REMAINS TO BE SOMEWHAT WET FROM RAIN
SHOWER ON FRIDAY NIGHT & SATURDAY.
DUST EMISSIONS APPEAR TO BE MINIMAL & BLOWING AWAY
FROM THE RNA.
ONE AIR SAMPLE IS COLLECTED.
NO ACCIDENTS ACCURED OR RECORDED.

Mike DeZevani
FIELD TECHNICIAN (Print Name)

Mike DeZevani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING Quality Corp.

Shift Start Date 4/10/2001

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: CLEAR & cool.

DESCRIPTION:

* 10:30 AM / TRI-STATE w/ A CREW OF SIX ON-SITE.

All appears to be in good condition.

Since the crew is preparing to take lunch break,
I can discuss the project w/ them.

The demolition contractor has uncovered another 100'
of transite blocks from the demo site.

The contractor is to bring the load to the RWA for
abatement.

WINDS ARE OUT OF WEST TODAY & DUST EMISSIONS FROM
THE EXCAVATION & DEMO SITE IS VISIBLE.

NO VISIBLE EMISSIONS IS VISIBLE FROM THE ABATEMENT
WORK AREA OR THE RWA.

NO ACCIDENT WAS REPORTED

ONE AIR SAMPLE WAS COLLECTED.

Mike Reynolds
FIELD TECHNICIAN (Print Name)

Mike +
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: ESOP-005

Project Name BOEING REALTY CORP.

Shift Start Date 4/11/2001

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: P/C & COOL

DESCRIPTION:

* 10:40 AM / TRI-STATE w/ A CREW OF SIX MEN - SITE.

THE SCOPE OF WORK REMAINS THE SAME FOR TODAY;

DUE TO THE CLOUDY SKY, THE DUST EMISSIONS FROM THE ADJACENT AREA TO RWA IS NOT VISIBLE.

THE CREW WORKS IN HARMONY & RATHER SLOWLY DUE TO THE NATURE OF WORK.

ACCESS TO THE RWA IS NOW LIMITED TO THE GATE ON THE WEST SIDE & THEREFORE LESS TRAFFIC DUST IS INTRODUCED TO THE WORK AREA.

* THE CREW TOOK ONE LUNCH BREAK & ONE SHORT BREAK.

* NO ACCIDENT WAS OBSERVED OR REPORTED.

* ONE AIR SAMPLE WAS COLLECTED.

* TRI-STATE PLANS TO BLACK-POLY THE PROPERTY FENCE AROUND THE RWA.

Mike + Revarni
FIELD TECHNICIAN (Print Name)

Mike + Revarni
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY Corp.

Shift Start Date 4/17/2001

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: CLEAR & WARM

DESCRIPTION:

* 10:00 AM / TRI-STATE w/ A CREW OF SIX MEN ON-SITE.
THE SCOPE OF WORK IS UNCHANGED.
TRI-STATE HAS INSTALLED A PLASTIC (GREEN) VISUAL BARRIER
AROUND THE REG. WORK AREA / PMA. THIS IS A GOOD IDEA.
ONE AIR SAMPLE WAS COLLECTED B/W 10:15 & 11:15 AM.
NO VISIBLE EMISSION WAS DETECTED.
NO ACCIDENTS HAVE BEEN REPORTED.
FEW ADDITIONAL HAZ. MANIFESTS ARE ACCUMULATED FOR
PROCESSING.
PERSONAL AIR SAMPLES FROM TRI-STATE WILL BE ANALYZED
BY ENVIRO. SOLUTIONS.
THE CREW IS WORKING A 10 HR. SHIFT.

Mike Reznani
FIELD TECHNICIAN (Print Name)

Mike Reznani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 4/13/2001

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: Cloudy & BREEZY

DESCRIPTION:

* 10:40 AM / ENVIRO. SOLUTIONS ON-SITE.

TRI-STATE w/ A CREW OF SIX MEN ON-SITE.

THE ABATEMENT ACTIVITIES CONTINUE AS BEFORE.

THE PROCESS HAS PICKED UP PACE.

ONE AIR SAMPLE WAS COLLECTED ON THE EAST SIDE OF THE
BURN DOWNTIME OF ACTIVITIES.

NO ACCIDENTS WERE REPORTED.

NO ADVERSE CONDITIONS EXIST.

CRITICAL BARRIERS / VISUAL BARRIERS ARE WELL IN PLACE.

* 1:40 PM / ENVIRO. SOLUTIONS OFF-SITE.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E600-1205

Project Name BOEING REALTY Corp.

Shift Start Date 4/11/2001

Project Location: UGTP Removal

Contractor: TRI-STATE

Weather Condition: P. CLOUDY & COOL

DESCRIPTION:

* 10:00 AM / ENVIRO. SOLUTIONS ON-SITE.

— TRI-STATE w/ A CREW OF SIX MEN ON-SITE.

WE HAVE BEEN INFORMED BY JOHNNY MARASCO & TRI-STATE
THAT MORE UNDERGROUND (GROUND) TRANSITE WATER PIPES HAVE BEEN
UNCOVERED FROM THE SUBJECT SITE & DUG-UP BY THE DEMO/GRADING
CONTRACTOR.


THE PIPE IS APPROX. 4,000 - 4,500 FEET LONG & MAY GO
EXPECTED TO BE AROUND THE PERIMETER OF THE SITE
& IT IS ABOUT 12" IN DIAMETER.

THE BIG PIECES OF THE PIPE ARE PLACED IN ALREADY PREPARED
DUMPSTERS & TURNTO WRAPPED BY TRI-STATE FOR DISPOSAL.

ONE AIR SAMPLE WAS COLLECTED OUTSIDE OF WORK AREA DNA.
NO ACCIDENTS WERE REPORTED.

NO ADVERSE CONDITION IS PRESENT.

ALL WORKERS ARE PROTECTED.


Mike Rezvan
FIELD TECHNICIAN (Print Name)


SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 4/23/01

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: CLEAR & MIL

DESCRIPTION:

- * 10:05 AM / ENVIRO. SOLUTIONS ON-SITE.
- TRI-STATE w/ A CREW OF SIX MEN - ON-SITE. THE WORK IS COMPRISED OF TWO PARTS. ✓ AS FOLLOWS:
- PROPER REMOVAL OF WATER TRANSITE PIPES.
- PROPER HANDLING & REMOVAL OF ELEC. TRANSITE PIPE FROM THE PRESENT RWA.
- ONE AIR SAMPLE IS COLLECTED ON-AIR.
- NO VISIBLE EMISSIONS DETECTED.
- NO ACCIDENT SEEN OR REPORTED.
- ONE PREPARED BIN IS ON-SITE FOR ALL TRANSITE PIECES.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

4/23/01
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-001

Project Name BOEING REALTY CORP.

Shift Start Date 4/25/2001


Project Location: UGTP REMOVAL SECT.

Contractor: TRI-STATE

Weather Condition: clear & MILD

DESCRIPTION:

* 10:00 AM / TRI-STATE w/ A CREW OF SIX (6) MEN ON-SITE.
THE SCOPE OF WORK IS UNCHANGED.
THE CREW CONTINUES TO SEPARATE TEANITE PIPES / COND. FROM ITS CONCRETE BLOCK ENCASEMENT.
ONE AIR SAMPLE IS COLLECTED ON-A.
NO VISIBLE EMISSIONS DETECTED.
NO ACCIDENT SEEN OR REPORTED BY TRI-STATE.
THE PROJECT COMPLETION IS @ 75% POINT.
THE CREW TOOK ONE LUNCH BREAK B/W 11: TO 12: NOON.
THE WINDS ARE CALM & TO JUST IS MIGRATING FROM THE ADJACENT CONSTRUCTION AREA.
* 1:30 PM / ENVIRO. SOLUTIONS OFF-SITE.


Mike DeZavani
FIELD TECHNICIAN (Print Name)


Jim Johnson
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: E500-065

Project Name BOEING REALTY CORP.

Shift Start Date 4/26/2001

Project Location: UGTP REMOVAL SECTION

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:38 AM / ENVIRO. SOLUTIONS ON-SITE.
TRI-STATE w/ A CREW OF SIX PEOPLE ON-SITE.
THE WINDS ARE CALM & OUT OF WEST & SOUTH WEST.
EMISSIONS ARE NOT VISIBLE @ THIS TIME.
THE CREW IS WORKING SLOWLY & CAUTIOUSLY.
THE ASBESTOS BIN REMAINS ON-SITE
NO EMISSION FROM THE REGULATED WORK AREA IS MADE VISIBLE.
ONE AIR SAMPLE IS COLLECTED USING LOW-FLOW AIR PUMP @
OUTSIDE OF WORK AREA JUST NORTHEAST OF THE RWA.
NO ACCIDENT WAS SEEN OR REPORTED.
THE PROJECT IS ABOUT 85% - 90% COMPLETE FOR THIS PHASE.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY Corp.

Shift Start Date 4/30/2001

Project Location: UGTP Removal

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD BREEZE

N.W.

DESCRIPTION:

* 10:40 AM / ENVIRO. SOLUTIONS ON-SITE.

TRI-STATE w/ ITS CREW OF FIVE WORKERS ON-SITE.

THE ABATEMENT OF TRANSITE CONDUIT / PIPE IN THIS SECTION OF THE PROPERTY / RWA CONTINUES.

THE WINDS ARE OUT OF NORTHWEST.

JUST SOUTH OF THE RWA / WORK AREA, AN EXCAVATOR IS MOVING SOIL. SOME OF THE VISIBLE EMISSIONS FROM THIS WORK IS ENTERING RWA.

THE RWA CONTINUES TO BE ISOLATED w/ VISUAL BARRIERS.

ONE SHORT AIR SAMPLE IS COLLECTED OUTSIDE OF THE RWA.

THIS PART / OF THE PROJECT IS ABOUT 90% COMPLETE.
PHASE

NO ACCIDENT WAS OCCURED OR REPORTED DURING THIS SHIFT.

NO VISIBLE EMISSION FROM THE RWA IS REPORTED.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE / DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING RECYCLING CORP.

Shift Start Date 5/1 & 5/2/2001

Project Location: UGTP / REMOVAL

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD.

DESCRIPTION:

*10:00 AM / TRI-STATE w/ A CREW OF FIVE MEN ON-SITE

DURING YESTERDAY (5/1) & TODAY, THE LOCATION OF OUR REGULATED WORK AREA (RWA) HAS CHANGED.

BOEING IS RELOCATING OUR WORK AREA TO THE OPPOSITE SIDE / OR WEST SIDE OF THE SITE.

ALL TRANSITE / CONCRETE BLOCKS ARE BEING TRANSPORTED OUT TO THE WEST & NORTH-WEST CORNER.

TRI-STATE'S JOB FOR THE NEXT COUPLE OF DAYS WILL BE TO ESTABLISH A NEW RWA & RESUME ABATEMENT.

NO AIR MONITORING DEEMED NECESSARY.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-005

Project Name BOEING REALTY CORP.

Shift Start Date 5/10/2001

Project Location: UHPP / REMOVAL

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD.

DESCRIPTION:

* 10:15 AM / TRI-STATE w/ A CREW OF FIVE ON-SITE.
THE CREW'S SCOPE OF WORK HAS REMAINED THE SAME.
THE RWA HAS EXPANDED TO SUPPLY A LARGER AMOUNT
OF TRANSIT BLOCKS OF ACM.
THE CREW IS WORKING CONSISTENTLY IN THE SAME AREA.
Nikko Demolition Contractor has demobilized their
equipment & materials from the site & therefore
no dust/visible is observed.
One air sample was collected downstream of work area.
No accident was reported.
Work progress w/o any adverse condition.
The area has visual barrier.

MIKE PREZIANI
FIELD TECHNICIAN (Print Name)

Mike Preziani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E800-005

Project Name BOEIGA / UGTP REMOVAL

Shift Start Date 5/14/ - 5/15/2001

Project Location: NORTH WEST CORNER

Contractor: TRI-STATE

Weather Condition: OVERCAST

DESCRIPTION:

* 10: AM / ENVIRO. SOLUTIONS ON-SITE.

TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.

THE SCOPE REMAINS TO BE

*- REMOVAL & SEPARATION OF TRANLITE ASBESTOS FROM THE CONCRETE BLOCKS & DISPOSING THE MATERIALS AS ACM.

THE WORK ON BOTH DAYS APPEARS TO BE CONSISTENT IN ACTIVITIES.

NO ADVERSE CONDITIONS EXIST.

THE WORK PERFORMED BY TRI-STATE IS THE ONLY WORK PENDING ON THIS PROPERTY.

THE CREW TOOK ONE LUNCH BREAK & ONE REG. BREAK. NO ACCIDENT WAS OBSERVED OR RECORDED DURING THE SHIFTS.

ONE AIR SAMPLE was COLLECTED EACH DAY @ Downstream OF WORK ACTIVITIES.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

REZVANI
(Signature)
(Date)



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING / VCTP REMOVAL

Shift Start Date 5/21/2001

Project Location: N.W. CORNER

Contractor: TRI-STATE

Weather Condition: OVERCAST & COOL

DESCRIPTION:

* 10:15 AM/ Enviro. Solution on-site.

TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.

OUR OBSERVATIONS INDICATE THE FOLLOWING:

1) THE RWA @ N.W. CORNER IS RESTRICTED & SECURED.

2) ALL HEAVY EQUIPMENT ARE IN GOOD WORKING CONDITION.

3) THE WORK AREA IS DEMARKATED WELL.

4) THE BINS ARE PREPARED W/ POLY. MOST BINS ARE EMPTY.

5) THE WORK AREA HAS A VISUAL BARRIER.

THE WORK IS PROGRESSING W/O INCIDENT.

NO EMISSION OR DUST IS DETECTED.

THE WORKERS ARE WELL PROTECTED.

Enviro. Solution collects two (2) air samples @ Dis. of work area as monitoring samples.

No, accidents were reported.

One lunch break was taken by TRI-STATE workers.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)


SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 5/22 - 5/24/2001

Project Location: UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: OVERCAST TO CLEAR

DESCRIPTION:

* 10:00 AM / ON EACH DAY OUR VISIT INDICATED THE FOLLOWING
* TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
AS NORMAL STATE OF PRACTICE, THE CREW IS PROTECTED
w/ RESPIRATOR PROTECTION, HARDHATS, TYVEK SUITS,
GOGGLES & BOOTS.
* LARGE PIECES OF TRANSITE CONTAINING CONCRETE WERE
BROUGHT FROM THE WEST SIDE OF THE RWA w/ A LARGE
BULLDOZER. THE SAME MACHINE BREAKS THE BLOCK & THEN
THE CREW MANUALLY REMOVES THE TRANSITE FROM THE CONC.
THE ABOVEUTOS TRANSITE PIECES ARE PLACED IN BAGS & THE
CONCRETE IS TRANSPORTED OUT OF THE RWA TO A PILE AREA.
OTHER DRILLING ACTIVITIES ARE ALSO IN PROGRESS IN THE AREA BUT
NO VISIBLE DUST EMISSION IS OBSERVED.
THE WINDS ARE GENERALLY OUT OF WEST & NORTHWEST.
* WE COLLECT ONE AIR SAMPLE DURING EACH MONITORING PHASE.
FROM THE OWA/DRWA.
THE CREW BREAKS FOR LUNCH EACH DAY FOR ONE HR.
NO ACCIDENT HAS BEEN REPORTED.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES001-005

Project Name BOEING REALTY CORP.

Shift Start Date ES001-005/29/2001

Project Location: UGTP REMOVAL / N.W. COR.

Contractor: TRI-STATE

Weather Condition: CLEAR & BREEZY

DESCRIPTION:

* 10:00 AM / ENVIRO. SOLUTIONS ON-SITE
TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
THE PERSONNEL OF THE SUBJECT CREW HAS NOT CHANGED.
THE SCOPE & EXECUTION OF WORK HAS NOT CHANGED.
ALL APPEARS TO BE IN ORDER.
DUST EMISSION IS VISIBLE BUT THIS DUST IS NOT FROM
ACTIVITIES RELATED TO ASBESTOS ABATEMENT.
THE WINDS ARE OUT OF THE N.WEST & WEST.
SIX 40 TON BINS ARE HERE ON-SITE & PREPARED.
THE BAGS CONTAINING ACM / TRANSITE ARE PLACED INSIDE OF
THESE BINS.
ONE SHORT DURATION AIR SAMPLE IS COLLECTED OUTSIDE OF RWA.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-025

Project Name BOEING REALTY CORP.

Shift Start Date 5/30 & 5/31/01

Project Location: N.W. CORNER / UGIP

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:30 AM / TRI-STATE w/ A CREW OF FIVE ON-SITE.
ENVIRO. SOLUTIONS ON-SITE.

THE SCOPE OF WORK REMAINS THE SAME FOR THE
CONTRACTOR.

THE BREEZ IS BLOWING FROM THE WEST / N. WEST & THE
GENERAL WORK AREA IS DUSTY.

THE WORK AREA IS TAPE & ISOLATED.

WE MET w/ FORTUNY MARASCO @ THE SITE & DISCUS THE
PROJECT'S PROGRESS.

NO ACCIDENTS REPORTED THIS SHIFT.

ONE AIR SAMPLE WAS TAKEN @ DOWNSTREAM ON EACH
DAY'S SHIFT.

Miles Rizvani
FIELD TECHNICIAN (Print Name)

John J. Murphy
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 6/1/2001

Project Location: ULTRP REMOVAL / NW.

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

- * 10:20 AM / ENVIRO SOLUTIONS ON-SITE.
 - TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
 - THE PROJECT STATUS IS AS FOLLOWS;
 - THE CREW IS IN THE PROCESS OF TRANSPORTING LARGE CONCRETE PIECES CONTAINING ASBESTOS TRANSITE CONDUIT FROM ONE SIDE OF THE WORK AREA TO THE BASIC CUTTING / BREAKING AREA.
 - THE REMOVED & OR SEPARATED ASBESTOS TRANSITE IS PLACED INSIDE PLASTIC BAGS & BROUGHT IN A SAFE CORNER & THEN BAGS ARE TIED & PLACED INSIDE THE 40 TARD BIN.
 - TRI-STATE COLLECTS PERSONAL AIR SAMPLES.
 - ENVIRONMENTAL SOLUTIONS COLLECTS AIR SAMPLES @ OUTSIDE OF THE WORK AREA
 - NO ACCIDENT WAS RECORDED DURING THIS SHIFT.
 - WE DISCUSSED THE PROJECT'S PROGRESS w/ TRI-STATE ON-SITE.
 - * 1:30 PM / ENVIRO. SOLUTIONS OFF-SITE.

Mike DeZavani
FIELD TECHNICIAN (Print Name)

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 6/5/2001

Project Location: N.W. @ UGTP REMOVAL

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:30 PM / TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.
ENVIRO. SOUTIONS ON-SITE.

THE SCOPE OF WORK MAY HAVE EXPANDED BECAUSE MORE
TRANSITE PIPES HAVE BEEN UNCOVERED ON THE OTHER SIDE OF
THE SITE WHERE SOIL UNCOVERING IS GOING ON.

THE PROJECT PROGRESSES NORMALLY.

THE COMPLETION RATE IS @ 75-80% & GETTING LESS.

THE GENERAL WORK AREA IS DUSTY & DUST REMAINS
A VISIBLE PART OF THE PROJECT.

WATER IS USED AROUND THE IMMEDIATE WORK AREA.

NO ACCIDENTS ARE REPORTED.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: BSOO-005

Project Name BOEING REALTY CORP.

Shift Start Date 6/13 - 6/14/2001

Project Location: UGTP ABATE / M.W. CORN.

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:30 AM / ENVIRO. SOLUTIONS ON-SITE.

TRI-STATE W/ A CREW OF FIVE MEN HAS BEEN ON SITE
ON BOTH DAYS.

THE SCOPE OF WORK REMAINS THE SAME FOR BOTH WEDNESDAY
& THURSDAY.

OUR OBSERVATIONS ON BOTH DAYS INDICATE NO BREACH OF ACTIVITIES
OR ADVERSE CONDITIONS.

ON WEDNESDAY, 6/13/2001, GERALD ADKINSON INFORMED US
ABOUT TWO PEOPLE WHO WERE PHOTOGRAPHING THE RWA.

SINCE TRI-STATE IS ADHERING TO THE SPECIFICATION, WE
DO NOT BELIEVE THERE IS ANY REASON FOR CONCERN.

PREVAILING WINDS ON BOTH DAYS WERE FROM THE WEST.

THE GROUND REMAINS DRY FOR THE MOST PART & THUS
THE DUST IS EMINENT.

NO INJURIES RECORDED OR REPORTED DURING THESE TWO
DAYS.

ONE AIR SAMPLE WAS COLLECTED EACH DAY @
DOWNSTREAM OF RWA.

MIKE REVAMI
FIELD TECHNICIAN (Print Name)

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES 00-005

Project Name BOEING REALTY CORP.

Shift Start Date 6/12/2001

Project Location: UGTP ABATE / N.W. CORN.

Contractor: TRI-STATE

Weather Condition: CLEAR & MILK

DESCRIPTION:

* 12:05 AM ENVIRO. SOLUTIONS ON-SITE.

TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.

THE SCOPE OF WORK REMAINS THE SAME FOR BOTH, MONDAY & TUESDAY.

OUR OBSERVATIONS ON BOTH DAYS DO NOT INDICATE ANY ADVERSE CONDITIONS OR ANY BREACH FROM THE ORIGINAL SCOPE OF WORK.

PREVAILING WINDS ON BOTH DAYS WERE FROM THE WEST.

THE GROUND IS DRY & DUST IS EMINENT.

NO INJURIES RECORDED OR REPORTED DURING THESE TWO DAYS. ONE AIR SAMPLE WAS COLLECTED EACH DAY @ DOWNSTREAM OF REG. WORK AREA (R-WA).

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE . 6/12/01



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ESOC-005

Project Name BOEING REALTY CORP.

Shift Start Date 6/18 - 6/19/01

Project Location: UGTP REMOVAL / N.W.

Contractor: TPI-STATE

Weather Condition: CLEAR & WARM

DESCRIPTION:

THIS REPORT PRESENTS THE CONDITIONS @ THE SITE FOR THE SUBJECT PROJECT, ON THE 6/18 & 6/19.

* 10:35 AM/ ENVR. SOLUTIONS ON-SITE.

TPI-STATE w/ A CREW OF FIVE MEN ON-SITE.

THE SCOPE OF WORK FOR THESE TWO DAYS IS TO CONTINUE TO SEPARATE TRANSITE FROM CONCRETE & DISPOSE OF EACH ACCORDINGLY.

THE CONSTRUCTION CREW ON THE EAST SIDE OF THE WORK AREA HAS BROUGHT MORE CONCRETE & TRANSITE TO THE SITE.

THIS MAY ADD AN ADDITIONAL ONE WEEK TO THE LENGTH OF THE PROJECT. THE LAND REMAINS DRY & DUSTY, BUT THE BLOCK-BREAKING PROCESS IS DUST FREE.

EMISSIONS DOWN TO NOT VISIBLE.

NO INJURIES REPORTED OR OBSERVED.

ONE AIR SAMPLE WAS COLLECTED @ THE EQUIPMENT ROOM.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: ES00-005

Project Name BOEING REALTY Corp.

Shift Start Date 6/20 - 6/21/01

Project Location: UGTP REMOVAL / N.W.

Contractor: TRI-STATE

Weather Condition: CLEAR & WARM

DESCRIPTION:

* 10:30 AM / THIS REPORT PRESENTS THE CONDITIONS @
THE SUBJECT SITE FOR THE SUBJECT PROPERTY ON THE
WORK DAY OF JUNE 20 & JUNE 21.

@ 10:30 AM WE WERE ON SITE.

TRI-STATE w/ A CREW OF FIVE MEN ON-SITE.

THE SCOPE OF WORK FOR THE TWO DAYS WAS TO CONTINUE
TO BREAK CONCRETE BLOCKS, SEPARATE THE TRANSITE
PIPE/CONDUIT FROM THE CONCRETE & DISPOSE OF ACCORDINGLY.
NO INJURIES REPORTED.

TRI-STATE INFORMS US THAT SEVEN MORE WEEKS OF
WORK REMAINS.

ONE AIR SAMPLE WAS COLLECTED ON EACH DAY.

MIKE REZNANI
FIELD TECHNICIAN (Print Name)

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ESOO-0625

Project Name BOEING REALTY CORP.

Shift Start Date 6/25 - 6/26/01

Project Location: UGTP Removal / N.W.

Contractor: TRI-STATE

Weather Condition: CLEAR & WARM

DESCRIPTION:

* 10:30 AM / ENVIRO. SOLUTIONS ON-SITE.
TRI-STATE w/ A CREW OF 5 MEN ON-SITE.
THE SCOPE OF ABATEMENT REMAINS THE SAME.
THE CONDITIONS REMAIN THE SAME.
10 MORE CUBIC YARDS OF THE CONCRETE BLOCKS
WERE BROKEN & PROCESSED SINCE LAST FRIDAY.
ENVIRO. SOLUTIONS IS ANALYZING THE PERSONAL AIR
SAMPLES FOR TRI-STATE.
NO ACCIDENTS OR INJURY HAVE BEEN REPORTED.
ONE AIR SAMPLE WAS COLLECTED EACH DAY.

Mike Resavant
FIELD TECHNICIAN (Print Name)

Mike Resavant
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500 - 005

Project Name BOEING REALTY CORP.

Shift Start Date 6/23 - 7/2 / 2001

Project Location: UGTP REMOVAL / N.W.

Contractor: TEI-STATE

Weather Condition: CLEAR TO P.C.

DESCRIPTION:

* 10:05 AM / TEI-STATE w/ A CREW OF FIVE ON-SITE.

ENVIRO. SOLUTIONS ON-SITE.

THE SCOPE OF WORK IS UNCHANGED.

THE CONCRETE BROKEN PIECES & OTHER DEBRIS ACCUMULATES ON THE EAST SIDE. THE CONCRETE w/ ASBESTOS REMAINS ON THE WEST SIDE.

TEN TONS OF CONCRETE & ASBESTOS HAVE BEEN BROKEN UP & PROCESSED.

ON THURSDAY 6/27/01, TWO MORE HAZARDOUS MANIFESTS WERE PROCESSED & SUBMITTED TO US FOR DOCUMENTATION.

THE ABATEMENT APPEARS TO BE PROGRESSING WELL.

NO ACCIDENT WAS REPORTED.

NO MUDHOPS OR ANY BREACH OF SLOPES WAS OBSERVED.

ONE AIR SAMPLE WAS COLLECTED EACH DAY FOR AIR MONITORING PROCESS ONLY.

MICHAEL PREZVANI
FIELD TECHNICIAN (Print Name)

SIGNATURE/DATE

7/2/01



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY Corp.

Shift Start Date 7/9/2001

Project Location: N.W. UGTP ABATE

Contractor: TRI-STATE

Weather Condition: CLEAR/WARM/BLIZZ.

DESCRIPTION:

* 10:10 AM / ENVIRO. SOLUTIONS ON-SITE.
~~EN TRI-STATE w/ A CREW OF SIX MEN ON-SITE.~~
~~THE CREW DID NOT WORK LAST THURSDAY.~~
~~WE OBSERVE THE CREW @ THIS TIME TO BE BREAKING CONCRETE & SEPARATING FROM TRANSIT PIPE/CONDUIT.~~
~~WINDS ARE STRONG OUT OF THE WEST.~~
~~NO DUST EMISSION IS OBSERVED FROM THE WORK AREA.~~
~~CREW TAKES LUNCH BREAK @ 11:00 AM.~~
~~TWO AIR SAMPLES COLLECTED OUTSIDE OF THE WORK AREA.~~
~~NO ACCIDENTS WERE OBSERVED OR REPORTED.~~
~~ONE MAN IS SUBSTITUTING FOR G. ADKISON FOR TODAY ONLY.~~

Mike Rezvan
FIELD TECHNICIAN (Print Name)


SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-205

Project Name BOEING REALTY CORP.

Shift Start Date 7/10 - 7/11/2001

Project Location: N.W. UGTP AREA

Contractor: TRI-STATE

Weather Condition: CLEAR & BREEZY

DESCRIPTION:

* 10:00 AM ENVIRO-SOLUTIONS ON-SITE.

TRI-STATE HAS SIX MEN ON-SITE.

THE SCOPE OF WORK FOR THIS WEEK IS A CONTINUATION OF WORK.

THERE IS STILL MUCH WORK TO BE DONE.

A LARGE PILE OF CONCRETE BLOCKS REMAINS ON-SITE.

TRI-STATE IS CONTINUING TO USE HEAVY EQUIPMENT IN ORDER TO BREAK THE CONCRETE.

THE SURFACE OF THE LAND REMAINS DRY & DUST FROM THE NEW-ACM / OWA REMAINS EMINENT.

TRI-STATE CREW TAKES ONE LUNCH BREAK & RETURNS TO WORK @ 12:15 PM.

NO ACCIDENTS WERE REPORTED ON EITHER DAY.

ONE AMBIENT AIR SAMPLE WAS COLLECTED EACH DAY.

THE PROJECT APPEARS 80-85% COMPLETE.

FOUR MORE WEEKS IS ANTICIPATED.

Mike Rezzani
FIELD TECHNICIAN (Print Name)

7-11-01
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY Corp.

Shift Start Date 7/16/2001

Project Location: N.W. TR REMOVAL

Contractor: TRI-STATE

Weather Condition: P.CLOUDY & MILD

DESCRIPTION:

- * 10:05 AM / ENVIR. SOLUTIONS ON-SITE.
TRI-STATE w/ A CREW OF SIX MEN ON-SITE.
OUR OBSERVATIONS INDICATE THE FOLLOWING:
• THE HEAVY HAMMER IS BREAKING CONCRETE BLOCKS
• A TWO (2) MAN CREW IS MANUALLY BREAKING THE
SMALLER PIECES OF CONCRETE TO SEPARATE THE ASBESTOS
TRANSITE.
• THE SUPERVISOR IS COLLECTING PERSONAL AIR SAMPLES.
• THE WATER TRUCK IS WETTING THE AREA.
• VISIBLE EMISSIONS OF DUST ARE NOT EVIDENT FROM OUR
WORK AREA.
• ENVIR. SOLUTIONS COLLECTS ONE AMBIENT AIR SAMPLE.
• WE DISCUSS THE PROJECT PROGRESS w/ G. ATKESON.
• NO ACCIDENT WAS RECORDED OR OBSERVED.

MIKE PERZVANI
FIELD TECHNICIAN (Print Name)

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: E500-105

Project Name BOEING REALTY CORP.

Shift Start Date 7/17-7/19/2001

Project Location: N.W. CORNER

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:00 AM / ENVIRO. SOLUTIONS ON-SITE.

TRI-STATE w/ A CREW OF SIX MEN ON-SITE.

THE WORK CONTINUES w/o ANY CHANGES IN THE SCOPE.

THE AIR SAMPLING STRATEGY CHANGED A LITTLE.

ON TUESDAY ONLY ONE AIR SAMPLE WAS COLLECTED.

ON MONDAY & WEDNESDAY, TWO AIR SAMPLES WERE COLLECTED.
AND TODAY ONE AIR SAMPLE IS BEING COLLECTED OUTSIDE OF
THE ZWA PERIMETER.

JOHNNY MARASCO w/ BOEING IS HERE ON-SITE TO OBSERVE &
CHECK THE PROGRESS.

NO ACCIDENT WAS OBSERVED OR RECORDED.

EMISSIONS OF DUST IS BEING CONTROLLED TO A MINIMUM.

ONE BREAK & ONE LUNCH-BREAK WAS TAKEN BY THE CREW.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

7/19/2001
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: 500-C05

Project Name BOEING REALTY CORP.

Shift Start Date 7/23-7/25/2001

Project Location: N.W. CORNER

Contractor: TRI-STATE

Weather Condition: CLEAR & MILD.

DESCRIPTION:

* 10:30 AM / TRI-STATE w/ A CREW OF SIX MEN ON-SITE.
ENVIRO. SOLUTIONS ON-SITE.

THE SITUATION @ THE SITE REMAINS UNCHANGED.

THE WINDS ARE BLOWING OUT OF SOUTHWEST ON BOTH
DAY & TEMP. IS MILD.

THE ONLY DUST EMISSION IS FROM THE STREET ON THE
WEST SIDE OF THE SITE.

BREAKING I, SEPARATING THE CONCRETE FROM THE TRANSITE.

THE TOOK OUT WHICH BREAK FOR BOTH DAY.

ON 7/25/2001, FOLLOWING MARACO W/ BOEING UNITED

THE SITE FOR PROGRESS OF ACTIVITIES.

* ONE AIR SAMPLE WAS TAKEN EACH DAY.

* NO ACCIDENT WAS OBSERVED OR NOTED.

Mike Reyzman

FIELD TECHNICIAN (Print Name)

Mike Reyzman

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 7/30 - 8/1/2001

Project Location: NW. CORNER / TRANSITE

Contractor: TRI-STATE

Weather Condition: CLEAR / MILD / BREEZY

DESCRIPTION:

* 10130 AM / ENVIRO-SOLUTIONS ON-SITE ON ALL THREE DAYS.
TRI-STATE w/ A CREW OF FOUR MEN ON-SITE.
THE WORK APPEARS TO BE PROGRESSING @ A FASTER PACE.
SOME OF THE ATTENTION OF TRI-STATE IS FOCUSED ON
THE TRANSPORTING THE CONTAMINATED SOILS ON THE EAST END
OF THE PROJECT.
THE WINDS ARE: OUT OF SOUTHWEST & WEST ON ALL THREE
DAYS OF WORK.
ACCORDING TO OUR OBSERVATIONS, ABOUT 90% OF THE ABATEMENT
HAS BEEN ACCOMPLISHED.
NO ACCIDENT HAS BEEN OBSERVED OR RECORDED.
ONE AIR SAMPLE WAS COLLECTED EVERY DAY.

MICHAEL R. REZVANI
FIELD TECHNICIAN (Print Name)

Liket L. [Signature]

SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: E500-005

Project Name BOEING REALTY CORP.

Shift Start Date 8-6-2001

Project Location: N.W. CORNER / TP ABATE

Contractor: TRI-STATE

Weather Condition: CLEAR & WARM

DESCRIPTION:

AT 10:40 PM / TRI-STATE w/ A CREW OF EIGHT (8) MEN ON-SITE.
ENVIRO. SOLUTIONS ON-SITE. TWO MORE MEN ARE LATER ADDED.
THE SCOPE OF WORK IS UNCHANGED.
WE ARE INFORMED THAT THE ABATEMENT IS 90% FINISHED.
TRI-STATE ESTIMATES ANOTHER 3-4 WEEKS OF WORK
ON-SITE.
TWO AIR SAMPLES @ PARALLEL POSITIONS ARE COLLECTED.
NO ACCIDENT WAS OBSERVED OR RECORDED FOR THE PERIOD
OF OBSERVATION.

Mike Bezzani
FIELD TECHNICIAN (Print Name)

Mike Bezzani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: ES500-005

Project Name BOEING REALTY CORP.

Shift Start Date 8/7 & 8/8/2001

Project Location: N.W. CORNER TO ABATE

Contractor: TRI-STATE

Weather Condition: CLEAR/WARM

DESCRIPTION:

* 10:22 AM / ENVIRO. SOLUTIONS ON-SITE FOR BOTH DAYS.

TRI-STATE HAS CUT DOWN ON THE NUMBER OF THE CREWS &

@ THIS TIME HAS FIVE (5) MEN ON-SITE.

THE SCOPE OF WORK HAS BEEN UNCHANGED.

THE CREW IS CONTINUING WITH THE BREAKING OF CONCRETE &
SEPARATING THE ASBESTOS FROM THE CONCRETE & BAGGING THE ACM
TRANSITE IN CLEAR PLASTIC BAGS.

THE DUST FROM THE SOUTHERN HALF OF THE PROPERTY IS AFFECTING
THE DUST EMISSION LEVELS IN THE ASBESTOS RMA.

THE CREW TAKES ONE LUNCH BREAK EACH DAY.

NO ACCIDENT WAS OBSERVED ON EITHER DAY.

ONE AMBIENT (OWA) AIR SAMPLE WAS COLLECTED EACH DAY
BY ENVIRO-SOLUTIONS.

NO BREACH OF SCOPE HAS BEEN OBSERVED.

MIKE REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

FIELD REPORT

2601 E. Chevy Chase Drive, Glendale, CA 91206

Job No.: ES 00-005

Project Name BOEING REALTY CORP.

Shift Start Date 8/1 - 8/13/2001

Project Location: N.W. TP ABATEMENT

Contractor: TEI-STATE

Weather Condition: CLEAR & MILD

DESCRIPTION:

* 10:00 AM / TEI-STATE w/ A CREW OF FIVE MEN ON-SITE.

THE SCOPE OF WORK IS UNCHANGED.

THE WORK IS 90% - 95% COMPLETE.

WINDS ARE OUT OF THE WEST & N.WEST & DUST
CONTINUES TO BE A PROBLEM.

THE REGULATED WORK AREA CONTINUES TO BE WETTED
& DUST EMISSIONS UNDER CONTROLLED ENVIRONMENT.

ENVIRO. SOLUTIONS COLLECT ONE AIR SAMPLE EACH DAY.

THE AIR SAMPLE ANALYSES CONTINUE TO INDICATE
FIBER CONCENTRATION LEVELS THAT ARE BELOW PER-
MISSIBLE EXPOSURE LIMIT (PEL).

NO ACCIDENT WAS OCCURRED OR OBSERVED DURING THE
PAST TWO SHIFTS.

MICHAEL REZVANI
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

FIELD REPORT

Job No.: ES00-005

Project Name BOEING REALTY CORP.

Shift Start Date 8/15 - 8/20/2001

Project Location: N.W. CORNER / TPP.

Contractor: TRI-STATE

Weather Condition: CLEAR & WARM.

DESCRIPTION:

• 10:30 AM, ENVIRO SOLUTIONS ON-SITE ON WORK CONDUCTED DURING THIS WEEK. TRI-STATE w/ A CREW OF FIVE MEN & SUPERVISOR ON-SITE ALL DAYS OF THE WEEK. BY WEDNESDAY 8/15/2001 ALL WORK ASSOCIATED WITH BREAKING OF CONCRETE & SEPARATING TRANSITE PIPES HAD BEEN COMPLETED.
THE REMAINING WORK SCOPE IS TO SWEEP BY VISUAL INSPECTION THE ENTIRE WORK AREA & PICK UP ALL REMAINING PIECES OF TRANSITE ON THE GROUND.
OF WORK IS
TODAY ON MONDAY 8/20/2001, THE REMAINS TO BE:
• CLEARING ALL RESIDUAL JUNK FROM SITE.
• ABATING ANY ADDITIONAL FINDING OF TRANSITE BY CONTRACTORS.
• DEMOBILIZING AFTER SUBSTANTIAL COMPLETION.
NO ADDITIONAL AIR SAMPLING DEEMED NECESSARY.
OUR OBSERVATIONS DID NOT INDICATE ANY ACCIDENT OR RECORDED INJURIES.

Mike Rezvani
FIELD TECHNICIAN (Print Name)

Mike Rezvani
SIGNATURE/DATE

EXHIBIT II

AIR SAMPLING REPORTS

Environmental Solutions
Assessment - Engineering - Management



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATION

JOB NUMBER: E300-005

PROJECT NAME: BOEING REALTY

CLIENT: BOEING REALTY CORP.

CONTRACTOR TRI-STATS

PROJECT MANAGER: MIKE PAVANI TECHNICIAN: _____

SAMPLE NO	DATE	PUMP #	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
			TIME ON					
			TIME OFF					
A-01	1/16/01	LF01	10:40	120	360	OWA / D.S.	TRANSITE	<0.01 ^{f/c}
			3l/m	12:40			REMOVAL	MR
A-02	1/18/01	LF01	10:45	120	360	OWA / D.S.	TRANSITE	<0.01 ^{f/c}
			3l/m	12:45			REMOVAL	MR
A-03	1/22/01	LF01	10:50	90	360	OWA / D.S.	TRANSITE PIPE	<0.01 ^{f/c}
			4l/m	12:20			REMOVAL	MR
A-04	3/05/01	LF01	10:40	120	480	OWA / D.S.	TRANSITE PIPE	<0.01 ^{f/c}
			4l/m	12:40			REMOVAL	MR
A-05	3/08/01	LF01	10:45	90	270	OWA / D.S.	TRANSITE PIPE	<0.01 ^{f/c}
			3l/m	12:15			REMOVAL	MR
A-06	3/12/01	LF01	10:47	120	360	OWA / D.S.	TRANSITE PIPE	<0.01 ^{f/c}
			3l/m	12:47			REMOVAL	MR
A-07	3/10/01	LF01	10:35	120	360	OWA / D.S.	TRANSITE PIPE	<0.01 ^{f/c}
			3l/m	12:35			REMOVAL	MR
A-08	3/19/01	LF01	10:50	60	180	OWA / D.S.	TRANSITE PIPE	<0.01 ^{f/c}
			3l/m	11:50			REMOVAL	MR



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATION

JOB NUMBER: E500-005

PROJECT NAME: Boeing Realty / UGTR CLIENT: Boeing Realty Corp.

CONTRACTOR TRI-STATE

PROJECT MANAGER: Mike Rezvani TECHNICIAN: _____

SAMPLE NO	DATE	PUMP #	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
			TIME ON TIME OFF					
A-09	03/26/01	LF1	11:05 <u>31/m</u>	90 <u>12:35</u>	270	DOWN STREAM OWA	TRANSITE PIPE REMOVAL	<0.01 f/c MR
A-10	3/28/01	LF1	10:47 <u>31/m</u>	60 <u>11:47</u>	180	" "	" "	.09 f/c .13 f/c MR
A-11	4/5/01	LF1	10:50 <u>31/m</u>	80 <u>12:10</u>	240	" "	" "	<0.01 f/c MR
A-12	4/9/01	LF1	10:13 <u>31/m</u>	60 <u>11:43</u>	160	" "	" "	.019 f/c MR
A-13	4/10/01	LF1	10:50 <u>31/m</u>	120 <u>12:50</u>	360	" "	" "	.081 f/c MR
A-14	4/11/01	LF4	10:30 <u>31/m</u>	80 <u>12:10</u>	240	OWA DOWN STREAM	TRANSITE PIPE REMOVAL	.050 f/c MR
A-15	4/14/01	LF1	10:21 <u>31/m</u>	60 <u>11:21</u>	180	" "	" "	.047 f/c MR
A-16	4/17/01	LF1	10:15 <u>31/m</u>	60 <u>11:15</u>	150	" "	" "	.061 f/c MR

**ENVIRONMENTAL SOLUTIONS**

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATIONJOB NUMBER: ES00-005PROJECT NAME: VGTF REMOVALCLIENT: Boeing Realty Corp.CONTRACTOR TRI-STATEPROJECT MANAGER: Mike Rosario TECHNICIAN: _____

SAMPLE NO	DATE	PUMP #	TIME ON TIME OFF	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
A-17	4/18/01	LFI	10:50 3 l/m	60 11:50	180	OWA / D.S. NORTH EAST	MONITORING	0.047 f/c MR	
A-18	4/19/01	LFI	10:08 3 l/m	70 11:18	210	" "	" "	0.059 f/c MR	
A-19	4/23/01	LFI	10:16 3 l/m	60 11:16	180	" "	" "	0.666 f/c MR	
A-20	4/25/01	LFI	10:08 3 l/m	60 11:08	180	" "	" "	0.080 f/c MR	
A-21	4/26/01	LFI	10:38 4 l/m	100 12:18	400	" "	" "	0.39 f/c MR	
A-22	5/1/01	LFI	10:31 4 l/m	70 11:41	260	OWA DOWNSTREAM NORTH	" "	0.015 f/c MR	
A-23	5/10/01	LFI	10:38 4 l/m	70 11:48	260	" "	" "	0.043 f/c MR	
A-24	5/14/01	LFI	10:07 3 l/m	120 12:07	360	" "	MONITORING	0.033 f/c MR	



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATION

JOB NUMBER: ES00-005

PROJECT NAME: Boeing/VGTP Removal CLIENT: BOEING REALTY CORP.

CONTRACTOR TRI-STATE

PROJECT MANAGER: MIKE RELVANI TECHNICIAN: _____

SAMPLE NO	DATE	PUMP #	TIME ON TIME OFF	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
A-25	5/15	LFI	10:09 3 l/m	90 11:39	270	DOWNSTREAM WIND / MOB	MONITORING CLASS II	0.01 f/u MR	
A-26	5/16	LFI	10:15 3 l/m	120 12:15	360	" "	" "	0.015 f/u MR	
A-27	5/17	LFI	10:22 3 l/m	80 11:42	240	" "	" "	0.022 f/u MR	
A-28	5/21	LFI	10:40 2.5 l/m	100 12:20	250	DOWNSTREAM N.W. CORNER	MONITORING MR	0.015 f/u MR	
A-29	5/21	LF2	10:40 2.5 l/m	100 12:20	250	" "	" "	0.020 f/u MR	
A-30	5/22	LFI	10:31 2.5 l/m	110 12:21	275	" "	" "	0.043 f/u MR	
A-31	5/23/	LF2	10:15 3 l/m	120 12:15	360	" "	" "	0.061 f/u MR	
A-32	5/24/	LFI	10:30 3 l/m	60 11:50	240	" "	" "	0.050 f/u MR	

**ENVIRONMENTAL SOLUTIONS**

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATIONJOB NUMBER: ESCO - 005PROJECT NAME: VGTP ABATEMENTCLIENT: Boeing Realty Corp.CONTRACTOR TECH STATEPROJECT MANAGER: Mike Pizzani

TECHNICIAN: _____

SAMPLE NO	DATE	PUMP #	TIME ON TIME OFF	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
A-33	5/29	LF1	10:31 30/m	120	360	Downstream @ S.E. corn.	MONITORING	0.044 f/c	MR
A-34	5/30	LF2	10:40 20/m	90	180	~	~	0.062 f/c	MR
A-35	5/31	LF1	10:43 30/m	120	360	~	~	0.069 f/c	MR
A-36	6/4	LF4	10:40 30/m	120	360	~	~	0.061 f/c	MR
A-37	6/5	LF1	10:52 30/m	120	360	~	~	0.040 f/c	MR
A-38	6/5	LF2	10:50 30/m	100	300	~	~	0.071 f/c	MR
A-39	6/6	LF4	10:50 30/m	100	300	~	~	0.049 f/c	MR
A-40	6/7	LF1	10:42 30/m	100	300	~	~	0.033 f/c	MR

**ENVIRONMENTAL SOLUTIONS**

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATIONJOB NUMBER: ES000-005PROJECT NAME: ULTRAMAR TiresCLIENT: EWING PROPERTY CORP.CONTRACTOR: TE-STATEPROJECT MANAGER: Mike Reynolds TECHNICIAN: _____

SAMPLE NO	DATE	PUMP #	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
A-41	6/11/01	LF1	10:20	100	300 lt	DOWNSTREAM	AIR MONITORING	0.044 4/4
			30/m	12:00		S.W.C.R. PWA	Removal CLASS II	MR
A-42	6/12/01	LF2	10:24	100	300 lt	" "	" "	0.031 4/4
			30/m	12:04	" "	" "	" "	MR
A-43	6/13/01	LF1	10:32	110	330 lt	" "	" "	0.048 6/4
			30/m	12:22	" "	" "	" "	MR
A-44	6/14/01	LF2	10:40	100	200 lt	" "	" "	0.030 6/4
			20/m	12:10	" "	" "	" "	MR
A-45	6/18/01	LF1	10:42	100	200 lt	② CLEAN RM	" "	0.040 6/4
			20/m	12:22	AREA/ US	" "	" "	MR
A-46	6/19/01	LF1	10:48	110	220 lt	" "	" "	0.012 6/4
			20/m	12:38	" "	" "	" "	MR
A-47	6/20/01	LF1	10:35	100	200 lt	" "	" "	0.027 6/4
			20/m	12:15	" "	" "	" "	MR
A-48	6/21/01	LF2	10:40	120	240 lt	" "	" "	0.047 6/4
			20/m	12:40	" "	" "	" "	MR

**ENVIRONMENTAL SOLUTIONS**

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATIONJOB NUMBER: ES00-005PROJECT NAME: UGTP RemovalCLIENT: Boeing Realty Corp.CONTRACTOR TRI-STATEPROJECT MANAGER: MIKE REZVANI

TECHNICIAN: _____

SAMPLE NO	DATE	PUMP #	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
A-49	<u>6/25</u>	<u>LF1</u>	<u>10:40</u>	<u>100</u>	<u>200</u>	<u>NEAR CLR RM</u>	<u>AMB-AIR</u>	<u>0.050 f/cu</u>
			<u>3 l/m</u>	<u>12:10</u>		<u>AREA / ORWA</u>	<u>MONITORING</u>	<u>MR</u>
A-50	<u>6/26</u>	<u>LF2</u>	<u>10:43</u>	<u>90</u>	<u>270</u>	" "	" "	<u>0.053 f/cu</u>
			<u>3 l/m</u>	<u>12:13</u>		" "	" "	<u>MR</u>
A-51	<u>6/27</u>	<u>LF2</u>	<u>10:22</u>	<u>100</u>	<u>300</u>	" "	" "	<u>0.001 f/cu</u>
			<u>3 l/m</u>	<u>12:02</u>		" "	" "	<u>MR</u>
A-52	<u>7/2/01</u>	<u>LF2</u>	<u>10:07</u>	<u>120</u>	<u>360</u>	" "	" "	<u>0.0031 f/cu</u>
			<u>3 l/m</u>	<u>12:07</u>		" "	" "	<u>MR</u>
A-53	<u>7/9/01</u>	<u>LF2</u>	<u>10:17</u>	<u>110</u>	<u>330</u>	" "	" "	<u>0.0047 f/cu</u>
			<u>3 l/m</u>	<u>12:07</u>		" "	" "	<u>MR</u>
A-54	<u>7/9/01</u>	<u>LF1</u>	<u>10:17</u>	<u>110</u>	<u>330</u>	" "	" "	<u>0.0040 f/cu</u>
			<u>3 l/m</u>	<u>12:07</u>		" "	" "	<u>MR</u>
A-55	<u>7/10/01</u>	<u>LF1</u>	<u>10:14</u>	<u>90</u>	<u>270</u>	" "	" "	<u>0.0023 f/cu</u>
			<u>3 l/m</u>	<u>11:44</u>		" "	" "	<u>MR</u>
A-56	<u>7/11/01</u>	<u>LF1</u>	<u>10:07</u>	<u>90</u>	<u>270</u>	" "	" "	<u>0.0051 f/cu</u>
			<u>3 l/m</u>	<u>11:39</u>		" "	" "	<u>MR</u>



ENVIRONMENTAL SOLUTIONS

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATION

JOB NUMBER: ES00-005

PROJECT NAME: UGTP ABATEMENT CLIENT: BOEING REALTY CORP

CONTRACTOR TRI-STATE

PROJECT MANAGER: MIKE REZVANI TECHNICIAN: MIKE REZVANI

SAMPLE NO	DATE	PUMP #	TIME ON TIME OFF	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
A-57	<u>7/16/01</u>	<u>LF1</u>	<u>10:13</u> <u>20/m</u>	<u>110</u>	<u>220</u>	<u>N.W. OF THE</u> <u>WORK ARE</u>	<u>MONITORING</u> <u>TRANSITE ABATE</u>	<u>0.011f/u</u> <u>MR</u>	<u>n/a</u>
A-58	<u>7/16/01</u>	<u>LF4</u>	<u>10:14</u> <u>20/m</u>	<u>110</u>	<u>220</u>	<u>WEST OF THE</u> <u>WORK ARE</u>	<u>"</u> <u>"</u>	<u>0.020f/u</u> <u>MR</u>	<u>"</u>
A-59	<u>7/17/01</u>	<u>LF1</u>	<u>10:22</u> <u>30/m</u>	<u>120</u>	<u>360</u>	<u>"</u> <u>"</u>	<u>"</u> <u>"</u>	<u>0.012f/u</u> <u>MR</u>	<u>"</u>
A-60	<u>7/18/01</u>	<u>LF1</u>	<u>10:08</u> <u>20/m</u>	<u>120</u>	<u>240</u>	<u>"</u> <u>"</u>	<u>"</u> <u>"</u>	<u>0.018f/u</u> <u>MR</u>	<u>"</u>
A-61	<u>7/18/01</u>	<u>LF2</u>	<u>10:09</u> <u>20/m</u>	<u>110</u>	<u>220</u>	<u>"</u> <u>"</u>	<u>"</u> <u>"</u>	<u>0.010f/u</u> <u>MR</u>	<u>"</u>
A-62	<u>7/19/01</u>	<u>LF1</u>	<u>10:18</u> <u>20/m</u>	<u>100</u>	<u>200</u>	<u>"</u> <u>"</u>	<u>"</u> <u>"</u>	<u>0.008f/u</u> <u>MR</u>	<u>"</u>
A-63	<u>7/23/01</u>	<u>LF3</u>	<u>10:20</u> <u>2.50f/m</u>	<u>100</u>	<u>250</u>	<u>"</u> <u>"</u>	<u>"</u> <u>"</u>	<u>0.012f/u</u> <u>MR</u>	<u>"</u>
A-64	<u>7/23/01</u>	<u>LF1</u>	<u>10:22</u> <u>2.0f/m</u>	<u>100</u>	<u>200</u>	<u>"</u> <u>"</u>	<u>"</u> <u>"</u>	<u>0.008f/u</u> <u>MR</u>	<u>"</u>

**ENVIRONMENTAL SOLUTIONS**

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATIONJOB NUMBER: ES00-005PROJECT NAME: UGTP ABATEMENT

CLIENT:

BOEING REALTY Corp.CONTRACTOR TRI-STATEPROJECT MANAGER: MIKE REZVANI TECHNICIAN: MIKE REZVANI

SAMPLE NO	DATE	PUMP #	TIME ON TIME OFF	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
A-65	7/24/01	LF1	10:35 20/m	90 12:05	180	N.W. CORNER D. STREAM	MONITORING TRANSITE ABATE	0.008 f/c MR	
A-66	7/25/01	LF2	10:41 30/m	90 12:11	270	" "	" "	0.012 f/c MR	
A-67	7/30/01	LF1	10:40 3 P/m	120 12:40	240	" "	" "	<0.01 f/c MR	
A-68	7/31/01	LF1	10:22 20/m	100 12:02	200	" "	" "	0.022 f/c MR	
A-69	8/1/01	LF1	10:42 2.00/m	120 12:42	240	" "	" "	0.0073 f/c MR	
A-70	8/2/01	LF1	10:37 2.50/m	90 12:07	225	" "	" "	0.0137 f/c MR	
A-71	8/6/01	LF1	10:43 20/m	90 12:13	180	" "	" "	0.008 f/c MR	
A-72	8/6/01	LF2	10:43 2 P/m	90 12:13	180	" "	" "	0.015 f/c MR	

**ENVIRONMENTAL SOLUTIONS**

PLANNING • ENGINEERING • MANAGEMENT

2601 E. Chevy Chase Drive, Glendale, CA 91206

AIR SAMPLE DOCUMENTATIONJOB NUMBER: E800-005PROJECT NAME: UGTP ABATEMENTCLIENT: BOEING REALTY CORP.CONTRACTOR TFI-STATEPROJECT MANAGER: MIKE REZVANITECHNICIAN: MIKE REZVANI

SAMPLE NO	DATE	PUMP #	DURATION	VOLUME	LOCATION	OPERATION	AFC READER	QA/QC READER
			TIME ON					
			TIME OFF					
A-73	8/7/01	LFI	10:36	100	200 lt	OWA / WEST OF ACTIVITIES	ABATEMENT MONITORING	<0.01 f/c MR
			20/m	12:16		" "	" "	
A-74	8/8/01	LFI	10:30	100	300 lt	" "	" "	0.0156 f/c
			30/m	12:10		" "	" "	MR
A-75	8/9/01	LFI	10:05	120	240 lt	" "	" "	0.012 f/c
			20/m	12:05		" "	" "	MR
A-76	8/13/01	LFI	10:15	120	240 lt	" "	" "	0.020 f/c
			20/m	12:15		" "	" "	MR
A-7	8/11/01	LFI	10:00	65	130 lt	" "	" "	<0.01 f/c
			20/m	11:05		" "	" "	MR
A-78	8/15/01	LFI	11:04	60	180 lt	" "	" "	<0.01 f/c
			30/m	12:04		" "	" "	0.022 f/c MR
A-79	8/16/01	LF2	10:47	60	160 lt	" "	" "	0.022 f/c
			20/m	12:07		" "	" "	MR
A-80	8/16/01	LFI	10:47	60	160 lt	" "	" "	0.032 f/c
			20/m	12:07		" "	" "	MR

EXHIBIT III

HAZARDOUS MANIFESTS

NOTICE AND CERTIFICATION

The waste identified on manifest number 26711624 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: DOUGLASS AIRCRAFT CO M/S 000910020

ADDRESS: 190 1/2 & VONMAYER TORRANCE, CA 90506

James A. Johnson

Print name

James A.

Signature

JAM

Title

6-2 6-01

Date

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5 1 0 0 0 1	Manifest Document No. 0 1	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.			
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20711624						
4. Generator's Phone (562) 496-6524) CONTACT:		B. State Generator's ID						
5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 766 S. AVON AZUSA, CA 91702		C. State Transporter's ID [Reserved.]						
6. US EPA ID Number C A R 0 0 0 0 1 7 6 5 7		D. Transporter's Phone ((626) 969-1384)						
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]						
8. US EPA ID Number		F. Transporter's Phone						
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID						
10. US EPA ID Number C A D 0 0 9 0 0 7 6 2 6		H. Facility's Phone ((626) 334-0719)						
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) RG, ASBESTOS, 9, NA 2212, PGIII		12. Containers No. 0 0 2	Type C M	13. Total Quantity 00040	14. Unit Wt/Vol Y	I. Waste Number State 151 EPA/Other		
b.						State EPA/Other		
c.						State EPA/Other		
d.						State EPA/Other		
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.						
15. Special Handling Instructions and Additional Information BDC 24 HRS EMERGENCY INFO/TAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE:MCDONNELL DOUGLRS 190TH & NORMANDIE TORRANCE, CA 90546								
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.								
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.								
Printed/Typed Name GERALD ADKINSON		Signature Signature		Signature Agent Signature		Month 06	Day 26	Year 01
17. Transporter 1 Acknowledgement of Receipt of Materials								
Printed/Typed Name MIKE HARGAN		Signature Signature		Signature Signature		Month 06	Day 26	Year 01
18. Transporter 2 Acknowledgement of Receipt of Materials								
Printed/Typed Name		Signature				Month	Day	Year
19. Discrepancy Indication Space								
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

GENERATOR

TRANSPORTER

FACILITY

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CIA D 0 8 6 5 1 0 0 0 5 3 1 4 0 1	Manifest Document No. 0 1	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT CO. M/SD 009/0020 3855 LAKWOOD BLVD., LONG BEACH, CA. 90846		A. State Manifest Document Number 99831401				
4. Generator's Phone (562) 498-6524)		B. State Generator's ID				
5. Transporter 1 Company Name LIGHTING RESOURCES, INC.		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number C A E 1 0 0 0 8 2 7 7 5 1 3		D. Transporter's Phone (909) 923-7252				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number C A I 1 0 0 0 8 2 7 7 5 1 3		F. Transporter's Phone				
9. Designated Facility Name and Site Address LIGHTING RESOURCES, INC. 805 E. FRANCIS STREET ONTARIO, CA. 91761		G. State Facility's ID				
10. US EPA ID Number C A I 1 0 0 0 8 2 7 7 5 1 3		H. Facility's Phone (909) 923-7252				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number	
a. RQ, ENVIRONMENTALLY HAZARDOUS SUBSTANCE, SOLID, N.O.S., 9, UN3077, PGIII, (CONTAINING: POLYCHLORINATED BIPHENOLS.)		OD15 54	025PP	2	State 261 EPA/Other NON-RCRA	
b.					State	
c.					EPA/Other	
d.					State	
e.					EPA/Other	
J. Additional Descriptions for Materials Listed Above 11a. USED LIGHT BALLAST CAPACITORS 100%		K. Handling Codes for Wastes Listed Above a. -01- b. c. d.				
15. Special Handling Instructions and Additional Information 24HR. EMERGENCY PHONE: (800) 424-9300 RQ= 1LB. ERG#171 WEAR APPROPRIATE PROTECTIVE EQUIPMENT AND EYEWEAR						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name James A. V.		Signature S J V. 8/22/01		Month 02	Day 22	Year 2001
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Dawn G. Heppie		Signature D G. Heppie 8/22/01		Month 02	Day 22	Year 2001
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

Yellow: GENERATOR RETAINS

BOE-C6-0090237

NOTICE AND CERTIFICATION

The waste identified on manifest number 20711023 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR:

Douglas Aircraft Company
1410 41st Normandie, Torrance, CA 90504

Print name

Signature

Title

Date

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD00865100051000011	Manifest Document No. 011	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKEWOOD BL LONG BEACH, CA 90845		A. State Manifest Document Number 20711023				
4. Generator's Phone (562) 496-6524 CONTACT:		B. State Generator's ID				
5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 766 S. AYON AZUSA, CA 91702		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number CA0009007626		D. Transporter's Phone (562) 969-1384				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number CA0009007626		F. Transporter's Phone				
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID				
10. US EPA ID Number CA0009007626		H. Facility's Phone (626) 334-0719				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number	
a. RQ, ASBESTOS, 9, NA 2212, PGIII		1	00030	Y	State 151 EPA/Other	
b.					State EPA/Other	
c.					State EPA/Other	
d.					State EPA/Other	
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above				
		a. 03	b.			
		c.	d.			
15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE: MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90846						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <i>Pedro M. Aguirre</i>		Signature <i>Pedro M. Aguirre</i>		Month	Day	Year
TRANSPORTER 17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <i>PEDRO M. AGUIRRE</i>		Signature <i>Pedro M. Aguirre</i>		Month	Day	Year
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
FACILITY 19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

NOTICE AND CERTIFICATION

The waste identified on manifest number 20659701 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: DOUGLAS AIRCRAFT COMPANY M/S 0009 16020

ADDRESS: 3855 LAKWOOD BX LONG BEACH, CA 90846

Conan Adcox

Print name

[Signature]

Title

2-06-01

Date

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>clad086510005; 100</i>	Manifest Document No. <i>011</i>	2. Page 1 of <i>1</i>	Information in the shaded areas is not required by Federal law.			
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKWOOD BL LONG BEACH, CA 90846 4. Generator's Phone (562) 496-6524		A. State Manifest Document Number 20659701						
5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 766 S. AYON AZUSA, CA 91702		B. State Generator's ID						
6. US EPA ID Number <i>CABR010017557</i>		C. State Transporter's ID [Reserved.]						
7. Transporter 2 Company Name.		D. Transporter's Phone <i>(626) 969-1384</i>						
8. US EPA ID Number <i>CABP01010075125</i>		E. State Transporter's ID [Reserved.]						
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		F. Transporter's Phone						
10. US EPA ID Number <i>CABP01010075125</i>		G. State Facility's ID						
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type <i>001</i>	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number State 151 EPA/Other			
a. RQ. ASBESTOS, 9, NA 2212, PGIII					State EPA/Other			
b.					State EPA/Other			
c.					State EPA/Other			
d.					State EPA/Other			
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. b. c. d.						
15. Special Handling Instructions and Additional Information BDC 24 HRS EMERGENCY# INFOTRAC 1-800-535 5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE:McDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90546								
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.								
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.								
Printed/Typed Name <i>James A. Acosta, Supervisor</i>		Signature <i>[Signature]</i>		Month <i>02</i>	Day <i>00</i>	Year <i>2001</i>		
17. Transporter 1 Acknowledgement of Receipt of Materials								
Printed/Typed Name <i>John DeLoach</i>		Signature <i>[Signature]</i>		Month <i>02</i>	Day <i>00</i>	Year <i>2001</i>		
18. Transporter 2 Acknowledgement of Receipt of Materials								
Printed/Typed Name		Signature		Month	Day	Year		
19. Discrepancy Indication Space								
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

766 S. AYON AVE. • AZUSA, CA 91702
(626) 969-1384 • FAX (626) 969-4971**NON-HAZARDOUS WASTE DATA FORM**NAME DOUGLAS AIRCRAFT COMPANY M/S D009/0020CONTACT:
SITE: MCDONNELL DOUGLASADDRESS 3855 LAKWOOD BLEPA
I.D.
NO. C A D 0 8 6 5 1 0 0 0 5CITY, STATE, ZIP LONG BEACH, CA 90846PHONE NO. (562) 496-5524CONTAINERS: No. 2 CM VOLUME/CY Y WEIGHT/TONSTYPE: ROLL-OFF TRUCK DUMP TRUCK DRUMS CARTONS OTHER Roll-off/ Cube VanWASTE DESCRIPTION NON FRIBBLE ASBESTOS GENERATING PROCESS REMOVAL

COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM %

1. _____ 3. _____

2. _____ 4. _____

VOC-OVA READINGS _____

SITE ADDRESS 190TH & NORMANDIE TORRANCE, CA 90545PROPERTIES: pH N/A SOLID LIQUID SLUDGE SLURRY OTHER TRISTATEHANDLING INSTRUCTIONS: USE PROPER SAFETY EQUIPMENTTHE GENERATOR CERTIFIES THAT THE
WASTE AS DESCRIBED IS 100% NON-
HAZARDOUS.

TYPED OR PRINTED FULL NAME & SIGNATURE

12-20-00

DATE

TRANSPORTER INAME BDC SPECIAL WASTE SERVICES EPA
I.D. NO. C A R 0 0 0 1 7 6 5 7ADDRESS 766 S. AYON SERVICE ORDER NO. _____CITY, STATE, ZIP AZUSA, CA 91702 PICK UP DATE _____PHONE NO. (626) 969-1384 TYPED OR PRINTED FULL NAME & SIGNATURE

12-20-00

DATE

TRANSPORTER IINAME _____ EPA
I.D. NO. _____

ADDRESS _____ SERVICE ORDER NO. _____

CITY, STATE, ZIP _____ PICK UP DATE _____

PHONE NO. _____ TYPED OR PRINTED FULL NAME & SIGNATURE

12-20-00

DATE

TSD FACILITYNAME AZUSA LAND RECLAMATION EPA
I.D. NO. C A D 0 0 9 0 0 7 6 2 5 DISPOSAL METHODADDRESS 1201 W. GLADSTONE LANDFILL OTHER _____CITY, STATE, ZIP AZUSA, CA 91702PHONE NO. (626) 334-0719 TYPED OR PRINTED FULL NAME & SIGNATURE

12-20-00

DATE

GEN	OLD/NEW	L	A	TONS	SCAQMD 909 396 3456 21865 COBLEY, DIAMOND BAR
TRANS		S	B		
C/O		RT/CD		HWDF	

DISCREPANCY

NOTICE AND CERTIFICATION

The waste identified on manifest number 20710164 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: DOUGLAS AIRCRAFT COMPANY M/S 00091000

ADDRESS: 190 TA # 1000 WOLF TOWER, CA 90816

Print name

Signature

Title

Date

NOTICE AND CERTIFICATION

The waste identified on manifest number 20710165 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: _____

ADDRESS: _____

Print name Census Anderson

sign as agent.

Darlene D

Signature Pm

Title _____

5-8-01

Date _____

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550	UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 8 5 1 0 0	Manifest Document No. 0 1	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
	3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKEWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20710165				
	4. Generator's Phone (562)496-6524 CONTACT:		B. State Generator's ID				
	5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 766 S. AYON AZUSA, CA 91702		6. US EPA ID Number C A R 0 0 0 0 1 7 6 5 7		C. State Transporter's ID [Reserved.]		
	7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone (626) 969-1384		
	9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1281 W. GLADSTONE AZUSA, CA 91702		10. US EPA ID Number C A D 0 0 9 0 0 7 6 2 6		E. State Transporter's ID [Reserved.]		
	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) RG, ASBESTOS, 9, NA 2212, PGIII		12. Containers No. Type		13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
			0 0 2 C M		00000	Y	State 151
	b.						EPA/Other
	c.						State
	d.						EPA/Other
	J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE				K. Handling Codes for Wastes Listed Above		
					a. 03	b.	
					c.	d.	
	15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE:MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90546						
	16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
	If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
	Printed/Typed Name John Anderson		Signature John Anderson		Month 05	Day 08	Year 01
	17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name Leslie Brown		Signature Leslie Brown		Month 05	Day 08	Year 01	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name		Signature		Month	Day	Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Signature		Month	Day	Year	

DO NOT WRITE BELOW THIS LINE.

TRISTATE

766 S. AYON AVE. • AZUSA, CA 91702
(626) 969-1384 • FAX (626) 969-4971

NON-HAZARDOUS WASTE DATA FORM

TO BE COMPLETED BY GENERATOR	NAME <u>DOUGLAS AIRCRAFT COMPANY M/S D009/0020</u>				CONTACT: SITE: MCDONNELL DOUGLAS														
	ADDRESS <u>3855 LAKWOOD BL</u>				EPA I.D. NO.	<u>C A D 0 8 6 5 1 0 0 0 5</u>													
	CITY, STATE, ZIP <u>LONG BEACH, CA 90846</u>				PHONE NO. <u>(562) 496-6524</u>														
	CONTAINERS: No. <u>CM</u>		VOLUME/CY <u>10</u>	WEIGHT/TONS <u>Y</u>															
	TYPE: <input type="checkbox"/> ROLL-OFF <input type="checkbox"/> DUMP TRUCK <input type="checkbox"/> DRUMS <input type="checkbox"/> CARTONS <input checked="" type="checkbox"/> OTHER <u>RollOff/ Cube Van</u>																		
	WASTE DESCRIPTION <u>NON FRIABLE ASBESTOS</u>			GENERATING PROCESS <u>REMOVAL</u>															
	COMPONENTS OF WASTE		PPM %	COMPONENTS OF WASTE		PPM %													
	1. _____		3. _____	4. _____		_____													
	VOC-OVA READINGS _____																		
	SITE ADDRESS <u>190TH & NORMANDIE</u>			TORRANCE, CA 90846															
PROPERTIES: pH N/A <input checked="" type="checkbox"/> SOLID <input type="checkbox"/> LIQUID <input type="checkbox"/> SLUDGE <input type="checkbox"/> SLURRY <input type="checkbox"/> OTHER <u>TRISTATE</u>																			
HANDLING INSTRUCTIONS: <u>USE PROPER SAFETY EQUIPMENT</u>																			
THE GENERATOR CERTIFIES THAT THE WASTE AS DESCRIBED IS 100% NON-HAZARDOUS.			TYPED OR PRINTED FULL NAME & SIGNATURE		DATE														
TRANSPORTER I	NAME <u>BDC SPECIAL WASTE SERVICES</u>				EPA I.D. NO. <u>C A R 0 0 0 1 7 6 5 7</u>														
	ADDRESS <u>766 S. AYON</u>				SERVICE ORDER NO. _____														
	CITY, STATE, ZIP <u>AZUSA, CA 91702</u>				PICK UP DATE <u>1-27-00</u>														
	PHONE NO. <u>(626) 969-1384</u>				TYPED OR PRINTED FULL NAME & SIGNATURE														
TRANSPORTER II	NAME _____				EPA I.D. NO. _____														
	ADDRESS _____				SERVICE ORDER NO. _____														
	CITY, STATE, ZIP _____				PICK UP DATE _____														
	PHONE NO. _____				TYPED OR PRINTED FULL NAME & SIGNATURE														
TSD FACILITY	NAME <u>AZUSA LAND RECLAMATION</u>				EPA I.D. NO. <u>C A D 0 0 9 0 0 7 6 2 6</u>														
	ADDRESS <u>1201 W. GLADSTONE</u>				DISPOSAL METHOD <input type="checkbox"/> LANDFILL <input type="checkbox"/> OTHER _____														
	CITY, STATE, ZIP <u>AZUSA, CA 91702</u>																		
	PHONE NO. <u>(626) 334-0719</u>				TYPED OR PRINTED FULL NAME & SIGNATURE														
	<table border="1" style="width: 100%;"> <tr> <td>GEN</td> <td>OLD/NEW</td> <td>L</td> <td>A</td> <td>TONS</td> </tr> <tr> <td>TRANS</td> <td></td> <td>S</td> <td>B</td> <td></td> </tr> <tr> <td>C/O</td> <td></td> <td>RT/CD</td> <td>HWDF</td> <td>NONE</td> </tr> </table>				GEN	OLD/NEW	L	A	TONS	TRANS		S	B		C/O		RT/CD	HWDF	NONE
GEN	OLD/NEW	L	A	TONS															
TRANS		S	B																
C/O		RT/CD	HWDF	NONE															
SCAQMD 909 396 3456 21865 COPLEY, DIAMOND BAR																			
DISCREPANCY																			

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550 GENERATOR	UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C I A D 0 8 6 5 1 0 0 0 5 1 0 0	Manifest Document No. 0 1	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
	3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKWOOD BL LONG BEACH, CA 90846		4. Generator's Phone (562) 496-6524		CONTACT:		
	5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 766 S. HYON AZUSA, CA 91702		6. US EPA ID Number C A R A 0 0 0 0 1 7 6 5 7		A. State Manifest Document Number 20710166		
	7. Transporter 2 Company Name		8. US EPA ID Number		B. State Generator's ID 		
	9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		10. US EPA ID Number C I A D 0 0 9 0 0 7 6 2 6		C. State Transporter's ID [Reserved.] 		
	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) RQ, ASBESTOS, 9, NA 2212, PGIII		12. Containers No. 0 0 2	Type C M	13. Total Quantity 000075	14. Unit Wt/Vol V	I. Waste Number State 151 EPA/Other
	b.						State EPA/Other
	c.						State EPA/Other
	d.						State EPA/Other
	J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.				
	15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE: MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90846						
	16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
	If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
	TRANSPORTER	Printed/Typed Name Richard Rose	Signature Rose		Month 05	Day 17	Year 01
	Facility	17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Richard Rose	Signature Rose		Month 07	Day 09	Year 01
	Facility	18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature		Month	Day	Year
	Facility	19. Discrepancy Indication Space					
	Facility	20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name	Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

NOTICE AND CERTIFICATION

The waste identified on manifest number 20710166 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: DOUGLAS AIRCRAFT COMPANY M/S 0009/0020

ADDRESS: 140TH & NORWALK TORRANCE, CA 90846

Print name:

George Aikenson

Signature:

George Aikenson

Title:

PM

Date:

15-09-01

NOTICE AND CERTIFICATION

The waste identified on manifest number 20712609 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: DOUGLAS AIRCRAFT COMPANY INC WONG 10021

ADDRESS: 1907 1/2 NORMAN TECUMSEH RD 90846

Print name

Douglas Aircraft

Signature

J. D. Lee Signs as agent

Title

PM

Date

4-24-91

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

GENERATOR



TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CIA D 0 8 6 5 1 0 0 0 5	Manifest Document No. 3 1 4 0 0	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT CO. M/SD 009/0020 3855 LAKWOOD BLVD., LONG BEACH, CA. 90846		A. State Manifest Document Number 99831400				
4. Generator's Phone (562) 496-6524		B. State Generator's ID				
5. Transporter 1 Company Name LIGHTING RESOURCES, INC.		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number CAL 0 0 0 8 2 7 7 5 8		D. Transporter's Phone (909) 923-7252				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number		F. Transporter's Phone				
9. Designated Facility Name and Site Address LIGHTING RESOURCES, INC. 805 E. FRANCIS STREET ONTARIO, CA. 91761		G. State Facility's ID				
10. US EPA ID Number CAL 0 0 0 8 2 7 7 5 3		H. Facility's Phone (909) 923-7252				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. 02 4	13. Total Quantity Type D I M 192 0 0	14. Unit Wt/Vol P	I. Waste Number State 261 EPA/Other NON-RCRa	
a. RQ, ENVIRONMENTALLY HAZARDOUS SUBSTANCE, SOLID, N.C.S., 9, UN3077, PGIII, (CONTAINING: POLYCHLORINATED BIPHENYLIC.)					State	
b.					EPA/Other	
c.					State	
d.					EPA/Other	
J. Additional Descriptions for Materials Listed Above 11a. USED LIGHT BALLAST CAPACITORS 100%		K. Handling Codes for Wastes Listed Above a. -01- b.				
		c. d.				
15. Special Handling Instructions and Additional Information 24HR. EMERGENCY PHONE: (800) 424-9300 RQ= 1LB. ERG#174 WEAR APPROPRIATE PROTECTIVE EQUIPMENT AND EYEWEAR						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <i>John D. Smith</i>		Signature <i>John D. Smith</i>		Month 01	Day 01	Year 2001
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <i>Stan M. Nichols</i>		Signature <i>Stan M. Nichols</i>		Month 01	Day 20	Year 2001
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 0 8 6 5 1 0 0 0 5 1 0 0 0 1	Manifest Document No. C A R 0 0 0 0 1 7 6 5 7	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY P/S D009/0020 3855 LAKWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20711182				
4. Generator's phone (562) 496-6524) CONTACT:		B. State Generator's ID				
5. Transporter Company Name BDC SPECIAL WASTE SERVICES 766 S. AYON AZUSA, CA 91702		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number C A R 0 0 0 0 1 7 6 5 7		D. Transporter's Phone ((626) 969-1384)				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number		F. Transporter's Phone				
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID				
10. US EPA ID Number C A D 0 0 9 0 0 7 6 2 5		H. Facility's Phone ((626) 334-0719)				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) RQ, ASBESTOS, 9, NA 2212, PGIII		12. Containers No. 0 0 2	Type C M	13. Total Quantity 0 0 0 6 5	14. Unit Wt/Vol Y	I. Waste Number State 151 EPA/Other
b.						State EPA/Other
c.						State EPA/Other
d.						State EPA/Other
J. Additional Descriptions for Materials Listed Above ERIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03				b.
		c.				d.
15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5853 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE: MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90846						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name George Brown		Signature 		Month 04	Day 04	Year 01
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name Rodriguez		Signature 		Month 04	Day 04	Year 01
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

NOTICE AND CERTIFICATION

The waste identified on manifest number 2071182 and bearing California Waste Code 15C is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: DOUGLASS AIRCRAFT COMPANY MIS 000910020

ADDRESS: 3855 Luttrellwood BL. LONG BEACH CA 90846

Print name

Donald Anderson

Signature

[Signature]

Title

4-04-01

Date

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 9 6 5 1 0 0 0 5 1 0 0 0 1	Manifest Document No. 0 1 1 of 1	2. Page 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3835 LAKWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20710164			
4. Generator's Phone (562)496-6524 CONTACT: BDC SPECIAL WASTE SERVICES 766 S. AYON AZUSA, CA 91702		B. State Generator's ID 			
5. Transporter 1 Company Name 		C. State Transporter's ID [Reserved.] 			
6. US EPA ID Number C A R G 0 0 0 1 7 6 5 7		D. Transporter's Phone (626) 959-1384			
7. Transporter 2 Company Name 		E. State Transporter's ID [Reserved.] 			
8. US EPA ID Number 		F. Transporter's Phone 			
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID 			
10. US EPA ID Number C A D 0 9 0 0 7 6 2 6		H. Facility's Phone (526) 334-0719			
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
a. ASBESTOS, S, NA 2212, PGIII		0 0 2 C M	0 0 0 8 0	Y	State 151 EPA/Other
b.					State EPA/Other
c.					State EPA/Other
d.					State EPA/Other
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.			
15. Special Handling Instructions and Additional Information SDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE: MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90846					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name DEAN WILKINSON		Signature Dean Wilkinson 05/02/01			
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name BOB RUM		Signature Bob Rum 05/02/01			
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name 		Signature 05/02/01			
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name 		Signature 05/02/01			

DO NOT WRITE BELOW THIS LINE.

TRISTATE

NOTICE AND CERTIFICATION

The waste identified on manifest number 20712612 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: Douglas Aircraft Company
ADDRESS: 190th & Northwind, Torrance CA 90506

Census Anderson
Print name

Karen R. Anderson

Signature

JRW
Title

4-23-01

Date

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD0096510005100	Manifest Document No. A 11	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
GENERATOR	3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKEWOOD BL LONG BEACH, CA 90846 4. Generator's Phone (562)498-6524		A. State Manifest Document Number 20712612			
	5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 766 S. AYON AZUSA, CA 91702		B. State Generator's ID			
	6. US EPA ID Number CARA00017557		C. State Transporter's ID [Reserved.]			
	7. Transporter 2 Company Name 		D. Transporter's Phone (626) 969-1384			
	8. US EPA ID Number CAD0090075256		E. State Transporter's ID [Reserved.]			
	9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		F. Transporter's Phone			
	10. US EPA ID Number CAD0090075256		G. State Facility's ID			
	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) a. RG, ASBESTOS, 5, NA 2212, PGIII		12. Containers No. 008	13. Total Quantity C M 15-080	14. Unit Wt/Vol Y	I. Waste Number 151
	b.					State EPA/Other
	c.					State EPA/Other
d.					State EPA/Other	
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.				
15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTAC 1-800-535-5253 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1303 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE:MCDONNELL DOUGLAS 130TH & NORMANDIE TORRANCE, CA 90846						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name John DeLando		Signature John DeLando		Month 04	Day 23	Year 01
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name John DeLando		Signature J. DeLando		Month 04	Day 23	Year 01
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CAD00061510025100001	Manifest Document No. 01	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY K/S D809/0020 3855 LAKEWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20712609				
4. Generator's Phone (562)495-6524 CONTACT:		B. State Generator's ID				
5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 765 S. AYON AZUSA, CA 91702		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number CAR000017657		D. Transporter's Phone (626) 369-1384				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number CAD000900762E		F. Transporter's Phone				
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID				
10. US EPA ID Number CAD000900762E		H. Facility's Phone (626) 334-0719				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. 001	Type C M	13. Total Quantity 000140	14. Unit Wt/Vol Y	I. Waste Number 151
a. RQ, ASBESTOS, 9, NA 2212, PGIII						EPA/Other
b.						State
c.						EPA/Other
d.						State
				EPA/Other		
J. Additional Descriptions for Materials Listed Above ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03				b.
				c. d.		
15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY INFO TRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1385 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE: MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90546						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <i>John Stevens</i>		Signature <i>John Stevens</i>		Month 04	Day 21	Year 2001
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <i>Mike Harrell</i>		Signature <i>Mike Harrell</i>		Month 04	Day 21	Year 2001
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRIESTATE

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. CARD 0865100051000	Manifest Document No. 011	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D209/02020 3855 LAKWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20667191				
4. Generator's Phone (562)496-6524 CONTACT:		B. State Generator's ID				
5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 765 S. AYON AZUSA, CA 91702		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number CARR0800176517		D. Transporter's Phone (626) 969-1384				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number		F. Transporter's Phone				
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID				
10. US EPA ID Number CARD 08651007626		H. Facility's Phone (626) 334-0719				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number	
RG, ASBESTOS, 9, NA 2212, PGIII		8 8 2 C M	001080	Y	State 151 EPA/Other	
b.					State EPA/Other	
c.					State EPA/Other	
d.					State EPA/Other	
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.				
15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE: MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90505						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name CARL A. WILSON		Signature Stallard, Signature		Month 05	Day 01	Year 2001
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name JOHN P. DODD		Signature [Signature]		Month 05	Day 01	Year 2001
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name [Signature]		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5 1 0 0 0 1	Manifest Document No. 0 1	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKEWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20711926				
4. Generator's Phone (562) 496-6524 CONTACT:		B. State Generator's ID				
5. Transporter Company Name BDC SPECIAL WASTE SERVICES 766 S. AYON AZUSA, CA 91702		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number C A R 0 0 0 0 1 7 6 5 7		D. Transporter's Phone (626) 969-1384				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number		F. Transporter's Phone				
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID				
10. US EPA ID Number C A D 0 0 9 0 0 7 6 2 6		H. Facility's Phone (626) 334-0719				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) RG, ASBESTOS, 9, NA 2212, PGIII		12. Containers No. 0 2 2	Type C M	13. Total Quantity 00065	14. Unit Wt/Vol Y	I. Waste Number 151
a.						State EPA/Other
b.						State EPA/Other
c.						State EPA/Other
d.						State EPA/Other
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. 01				
		c. 01				
15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1385 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE:MCDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90846						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name Genesee Arson		Signature John (Signature)		Month 07	Day 15	Year 01
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name KIC and Roswell		Signature D		Month 07	Day 25	Year 01
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5 1 0 0	Manifest Document No. 0 1	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY P/S D009/0000 3655 LAKWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20708293				
4. Generator's Phone (562) 496-6524 CONTACT:		B. State Generator's ID				
5. Transporter 1 Company Name BURSPEX WASTE SERVICES 765 S. AYON AZUSA, CA 91702		C. State Transporter's ID [Reserved.]				
6. US EPA ID Number C A R 0 0 0 0 1 7 6 5 7		D. Transporter's Phone (626) 969-1384				
7. Transporter 2 Company Name		E. State Transporter's ID [Reserved.]				
8. US EPA ID Number		F. Transporter's Phone				
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLASTONE AZUSA, CA 91702		G. State Facility's ID				
10. US EPA ID Number C A D 0 0 9 0 0 1 7 E 2 6		H. Facility's Phone (626) 334-0719				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) RQ, ASBESTOS, 9, NA 2212, PGIII		12. Containers No. 0 0 2	Type C M	13. Total Quantity 0066P	14. Unit Wt/Vol Y	I. Waste Number State 151 EPA/Other
b.						State EPA/Other
c.						State EPA/Other
d.						State EPA/Other
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.				
15. Special Handling Instructions and Additional Information BLC 24HRS EMERGENCY# INFOTRAC 1-800-535-5053 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE:McDONNELL DOUGLAS 190TH & NORMANDIE TORRANCE, CA 90546						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <i>[Signature]</i>		Signature <i>[Signature]</i>		Month 06	Day 07	Year 01
17. Transporter 1 Acknowledgement of Receipt of Materials Karen Beeson						
Printed/Typed Name <i>[Signature]</i>		Signature <i>[Signature]</i>		Month 06	Day 07	Year 01
18. Transporter 2 Acknowledgement of Receipt of Materials Karen Beeson						
Printed/Typed Name <i>[Signature]</i>		Signature <i>[Signature]</i>		Month 06	Day 07	Year 01
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <i>[Signature]</i>						

DO NOT WRITE BELOW THIS LINE.

TRISTATE

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

TRANSPORTER

FACILITY

GENERATOR

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA, CALL 1-800-852-7550

GENERATOR

TRANSPORTER

FACILITY

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5 1 0 0 0 1 1 of 1	Manifest Document No. 0 1	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address DOUGLAS AIRCRAFT COMPANY M/S D009/0020 3855 LAKWOOD BL LONG BEACH, CA 90846		A. State Manifest Document Number 20710052				
4. Generator's Phone (562) 496-5524) CONTACT:		B. State Generator's ID 				
5. Transporter 1 Company Name BDC SPECIAL WASTE SERVICES 766 S. AVON AZUSA, CA 91702		C. State Transporter's ID [Reserved.] 				
6. Transporter 1 US EPA ID Number C A R 0 0 0 0 1 7 6 5 7		D. Transporter's Phone (626) 969-1384				
7. Transporter 2 Company Name 		E. State Transporter's ID [Reserved.] 				
8. Transporter 2 US EPA ID Number 		F. Transporter's Phone 				
9. Designated Facility Name and Site Address AZUSA LAND RECLAMATION 1201 W. GLADSTONE AZUSA, CA 91702		G. State Facility's ID 				
10. US EPA ID Number C A D 0 8 9 0 0 7 6 2 5		H. Facility's Phone (626) 334-0719				
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) RQ: ASBESTOS, 9, NA 2012, PGIII		12. Containers No. 0 0 2	Type C M	13. Total Quantity 0 0 0 6 0	14. Unit Wt/Vol Y	I. Waste Number 151
b.						State EPA/Other
c.						State EPA/Other
d.						State EPA/Other
J. Additional Descriptions for Materials Listed Above FRIABLE ASBESTOS CONTAINING WASTE		K. Handling Codes for Wastes Listed Above a. 03 b. c. d.				
15. Special Handling Instructions and Additional Information BDC 24HRS EMERGENCY# INFOTRAC 1-800-535-5253 EPA REGION IX 75 HAWTHORNE ST. SAN FRANCISCO, CA 94105 (415) 744-1305 ASBESTOS REMOVAL REQUIREMENT 40CFR61 (BAGGED SEALED & LABELED) SITE: MCDONNELL DOUGLAS 196TH & NORMANDIE TORRANCE, CA 90846						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name John A. Douglas		Signature 		Month 04	Day 26	Year 01
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name John A. Douglas		Signature 		Month 04	Day 26	Year 01
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

DO NOT WRITE BELOW THIS LINE.

TRISTATE

NOTICE AND CERTIFICATION

The waste identified on manifest number 20710052 and bearing California Waste Code 151 is subject to land disposal restrictions contained in CCR Title 22, Chapter 18, Article I. The waste meets the definition of a treated hazardous waste pursuant to Health and Safety Code, Section 25179.3 (1)(2), which states that waste is considered treated if the waste does not contain any substances above the Soluble Thresholds Limit Concentration values established in CCR Title 22, Chapter 18, Article II; and the waste is not prohibited from land disposal as provided in Health and Safety Code, Section 25179.6.

(waste analysis is attached for these wastes, where available)

As required by CCR Title 22, Chapter 18, Article I, the following certification is made for these wastes:

I warrant that I am an authorized representative of the generator. I certify under penalty of the law that the waste complies with the treatment standards specified in California Code of Regulations, Title 22, Division 4.5, Chapter 18, Section 66268.114. I believe that the information I submitted is true, accurate, and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

GENERATOR: Douglas Aircraft Company

ADDRESS: 19001 Mt. Mountain Avenue, El Segundo, CA 90245

* Print name

Signature

Title

Date

Environmental Solutions

Assessment - Engineering - Management
